

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011042/ATY3N2**Date:** 30/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00069082102

**Claimant Vehicle
No :** SJN9663K**Insured
Vehicle No :** GX9396P

Date of Loss: 26/10/2021

Nature of Claim: TP

Claim
No: SNM21D206149/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJN9663K**

Make & Model: HYUNDAI HD AVANTE, 1.6 Sunroof (A)

Engine No: G4FC9U611519

Reg. Date: 06/03/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U703436

Colour: Purple

Odometer: 196187 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,401.60	6,276.40	2,125.20	25.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,590.00	1,450.00	35.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,441.60	8,866.40	3,575.20	28.74
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	12,441.60	7,100.00	5,341.60	42.93

INSPECTION

Date of Assignment: 28/10/2021

Date Inspected: 28/10/2021 Inspected At:

Max Motors (HQ)
1 Kaki Bukit Ave 6, #01-98 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2021)

Parts: 143 HYUNDAI HD AVANTE 1.6 Sunroof (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN9663K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR PANEL LH	Distorted	1,289.00 FL	*1,141.00 FL
2	1		*REAR DOOR HINGE UPPER LH	Not Necessary	76.00 FL	*- FL
3	1		*REAR DOOR HINGE LOWER LH	Not Necessary	75.00 FL	*- FL
4	1		*REAR DOOR CHECKER LH	Not Necessary	89.00 FL	*- FL
5	1		*REAR DOOR INNER TRIM LH	Cracked	485.00 FL	*485.00 FL
6	1		*REAR DOOR LOCK ASSY	Damaged	584.00 FL	*291.00 FL
7	1		*REAR DOOR REGULATOR AND MOTOR LH	Damaged	533.00 FL	*385.00 FL
8	1		*REAR FENDER LH	Distorted	1,233.00 FL	*1,233.00 FL
9	1		*REAR FENDER INNER SHIELD LH	Torn	154.00 FL	*154.00 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
11	1		*REAR BUMPER	Repair	674.00 FL	*- FL
12	1		*REAR BUMPER RETAINER LH	Not Necessary	65.00 FL	*- FL
13	1		*REAR BUMPER RETAINER LH	Not Necessary	65.00 FL	*- FL
14	1		*REAR TAILLAMP LH	Not Necessary	343.00 FL	*- FL
15	1		*REAR KNUCKLE ARM LH	Damaged	424.00 FL	*424.00 FL
16	1		*REAR KNUCKLE ARM BEARING LH	Damaged	159.00 FL	*159.00 FL
17	1		*REAR LOWER ARM LH	Bent	384.00 FL	*384.00 FL
18	1		*REAR SHOCK ABSORBER LH	Bent	394.00 FL	*394.00 FL
19	1		*ROCKER PANEL LH	Dented	585.00 FL	*585.00 FL
20	1		*REAR DOOR TOP MOULDING LH	Not Necessary	118.00 FL	*- FL
21	1		*RIM	Cut	650.00 FS	*400.00 FS
22	1		*TYRE	Punctured	250.00 FS	*180.00 FS
23	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	40.00 FS	*30.00 FS
24	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
26	1		*JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
27	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
28	1		*REAR LH TRAILING ARM	Bent	344.00 FL	*344.00 FL
29	1		*REAR LH UPPER TRAILING ARM	Bent	378.00 FL	*378.00 FL
30	1		*REAR LH STAY ARM	Bent	321.00 FL	*321.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,192.00	7,648.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,790.40	1,371.60
Total Parts (\$\$)	8,401.60	6,276.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR LIGHTNING AND WIRING SYSTEM	New	100.00	30.00
2	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	150.00	80.00
3	REMOVE AND REFIT FUEL TANK	New	150.00	80.00
4	REMOVE,REFIT REAR REVERSE SENSOR	New	120.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
6	TRANSFER PARTS,ATTACHMENT FROM OLD DOOR TO NEW	New	200.00	80.00
7	PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS	New	1,400.00	1,000.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	800.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	100.00
10	REMOVE REAR UNDERCARRIAGE	New	350.00	220.00
11	PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			4,040.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >