

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Xiao Chun

Vehicle Number : SKN 1276 K
Vehicle Model : HONDA INSIGHT
Accident Date : 27.10.2021
Original Reg Date : 15.05.2014

Date : 28.10.2021
Chassis : JHMZE2850ES200086
TP Ins. : SOMPO

ESTIMATE

1	2 pc	Taillamps <i>LH cracked</i>	685.90	1,371.80	<i>685.90</i>
2	1 pc	Taillamps Inner Sealer <i>3 pc</i>	38.00	76.00	+
3	1 pc	Taillamps Lower Retainers <i>1 pc</i>	65.80	131.60	+
4	1 pc	Rear Bumper <i>Replaced</i>		785.90	+
5	1 pc	Rear Bumper Side Retainers <i>Replaced</i>	85.90	171.80	+
6	1 pc	Tailgate <i>Reps</i>		1,185.90	+
7	1 pc	Tailgate inner trim <i>3 pc</i>		589.60	+
8	1 pc	Tailgate outer garnish <i>1 pc</i>		385.90	+
9	1 pc	Tailgate logo <i>New</i>		98.70	✓
10	1 pc	Tailgate weatherstrip <i>New</i>		186.50	+
11	1 pc	Tailgate Insight emblem <i>3 pc</i>		95.80	✓
12	1 pc	Tailgate Hybrid emblem <i>1 pc</i>		97.60	✓
13	1 pc	Rear windscreen molding <i>New</i>		158.30	+
14	1 pc	Rear windscreen seal <i>New</i>		89.60	+
15	1 pc	Rear bumper <i>Replaced</i>		708.90	✓
16	2 pc	Rear bumper retainers <i>New</i>	89.60	179.20	<i>90</i>
17	1 pc	Rear lower bumper <i>Replaced</i>		485.90	✓
18	1 pc	Rear lower bumper cover <i>Cracked</i>		158.20	✓
19	2 pc	Rear bumper reflectors <i>Cracked</i>	95.30	190.60	+
20	1 pc	End panel <i>Replaced</i>		586.30	+
21	1 pc	End panel top garnish <i>Cracked</i>		198.60	✓
22	2 pc	Rear fender inner trim <i>3 pc</i>	458.20	916.40	+
23	2 pc	Rear fender inner cowling <i>1 pc</i>	158.60	317.20	+
24	1 pc	Spare Tyre top board <i>3 New</i>		425.80	+
25	1 pc	Spare Tyre sponge tool box <i>1 New</i>		398.50	+

9,592.10

Less 20% subtotal 1,918.42
7,673.68

2810.20

2248.16

Special Nett

1	1 pc	Windscreen Sealant <i>Not Nec</i>		60.00	<i>x.</i>
2	1 set	Rear number plate with case <i>Not m</i>		50.00	<i>x</i>
3	2 pcs	Rear fender inner cowling clips <i>Nec</i>	30.00	60.00	<i>20.</i>
4	2 Sets	Tailamps clips <i>Nec</i>	30.00	60.00	<i>20.</i>
5	1 set	Body Panel Joint Sealant <i>Not m</i>		120.00	<i>x.</i>
6	1 set	Tailgate Inner trim clips <i>Not m</i>		30.00	<i>x</i>
7	1 set	Rear bumper clips <i>Nec</i>		30.00	<i>✓</i>
8	1 pc	Reverse sensors <i>Damaged</i>		250.00	<i>200.</i>

270

Labour charge

Panel Beating		1,600.00	<i>500</i>
Spray painting		1,600.00	<i>600.</i>
Check Wiring on rear tailamp		120.00	<i>30</i>
Anti rust		120.00	<i>40.</i>
Remove and install windscreen		120.00	<i>x</i>
Remove and install tailgate inner trim		120.00	<i>x</i>
Remove and install reverse sensor		90.00	<i>50.</i>
		\$ 12,103.68	

1220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Adrian King.

L/s 29/10/21.

04 Days.

total: 3738.16

L/s: 3K2C

31C