

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011045/KUY3N2**Date:** 08/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00085872100

Claimant Vehicle No : GBJ7141D **Insured Vehicle No :** SMC136Y

Date of Loss: 01/10/2021 Nature of Claim: TP Claim No: SNM21D205653/C02/CHEES

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7141D**

Make & Model: TOYOTA HIACE, 2.8 D DX (A) Engine No: 1GD8383681

Reg. Date: 16/07/2019 (Man. Year: 2019) Chassis No: GDH2012005003

Colour: Silver Odometer: 17929 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,864.25	2,363.47	500.78	17.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	400.00	960.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,224.25	2,763.47	1,460.78	34.58
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	4,224.25	2,200.00	2,024.25	47.92
+ GST 7.00/7.00% (\$\$)	295.70	154.00	141.70	47.92
Nett Amount (\$\$)	4,519.95	2,354.00	2,165.95	47.92

INSPECTION

Date of Assignment: 29/10/2021

Date Inspected: 28/10/2021 Inspected At: 160 SIN MING DRIVE #03-18/19
SIN MING AUTOCITY
SINGAPORE 575722
REPAIRER: EM SOLUTION PTE LTD

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2021)
Parts:	213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7141D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented/Cut	683.30 FL	*548.20 FL
2	1		*FRT BUMPER BRACKET LH	Serviceable	192.20 FL	*- FL
3	1		*FRT BUMPER GARNISH LH	Serviceable	75.70 FL	*- FL
4	1		*HEADLAMP LH	Cut	2,543.10 FL	*2,543.10 FL
5	1		*FRT CORNER PANEL LH	Repair	264.70 FL	*- FL
6	1		*SET FRT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,804.00	3,136.30
- List Item Discount on L Items 25.00/25.00% (S\$)	939.75	772.83
Total Parts (S\$)	2,864.25	2,363.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE,REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	500.00	300.00
3	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	600.00	80.00
4	RUST PROOFING ON AFFECTED PORTIONS	New	180.00	0.00
Gross Labour Cost (S\$)			1,360.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >