### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

China Taiping Insurance (Singapore) Pte. Ltd. To:

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Chee So Chow Attn: Date: 01 Nov 2021

## **Preliminary Advice**

Insured Vehicle No : SMC136Y

TP Vehicle No : GBJ7141D : 01/10/2021 Accident Date Make : TOYOTA HIACE Assignment Date : 29/10/2021

Date of Inspection : 28/10/2021 Est. Duration of Repair

Inspection At : EM SOLUTION PTE LTD - SIN MING (HQ)

BLK 17 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR A

SINGAPORE 575675

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,224.25
Revised Amount	:S\$	2,763.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,763.48
Lump Sum Repair	:S\$	2,200.00

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
	let us have your authorisation.	

(		The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

Other comments: Please note that the preliminary advice amount (Revise) stated are subject to consistency ( X ) check, part prices and labour cost.