12/10/21, 10:51 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011046/VVY3N2

10/12/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00018032101

Claimant Vehicle No:

SJU9850A

Insured Vehicle YN5749X

No:

Date of Loss: 26/10/2021 Nature of Claim: TP

Claim

SNM21D206166/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJU9850A Reg No:

Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 2ZRA332992 Reg. Date: 06/01/2010 (Man. Year: 2009) Chassis No: ZGE200009606 Colour: Silver Odometer: 249712 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 215/50ZR17 Rear Tyre Size: 215/50ZR17 Front Left Side: Rear Left Side: Tourador 5 mm Tourador 5 mm Front Right Side: Rear Right Side: Tourador 5 mm Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,290.21	2,489.44	4,800.77	65.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,070.00	2,340.00	68.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	10,700.21	3,559.44	7,140.77	66.73
Approved Total (Overridden) (S\$)	2,850.00		
(S\$	10,700.21	2,850.00	7,850.21	73.37
+ GST 7.00/7.00% (S\$	749.01	199.50	549.51	73.36
Nett Amount (S\$	11,449.22	3,049.50	8,399.72	73.36

INSPECTION

Date of Assignment: 02/11/2021

Teamwork Garage Pte Ltd (HQ)

28/10/2021 Inspected At: 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Date Inspected:

Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Dec 2021)

Parts: M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJU9850A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR PANEL	Deformed	1,705.44 FL	*1,408.77 FL
2	1		*REAR RH DOOR INNER TRIM BOARD	Cut	1,085.15 FL	*865.59 FL
3	1		*REAR RH DOOR LOCK ASSY	Distorted	746.35 FL	*617.60 FL
4	1		*REAR RH DOOR REGULATOR	Distorted	260.81 FL	*260.81 FL
5	1		*REAR RH DOOR MOULDING	Serviceable	175.80 FL	*- FL
6	2		*REAR RH DOOR CHECKER	Serviceable	369.61 FL	*- FL
7	1		*REAR RH DOOR HANDLE	Repair	86.49 FL	*- FL
8	1		*REAR RH DOOR WEATHERSTRIP	Serviceable	214.50 FL	*- FL
9	1		*RH SIDE SKIRT	Repair	1,261.15 FL	*- FL
10	1		*FRONT RH DOOR PANEL	Repair	1,045.88 FL	*- FL
11	1		*FRONT RH DOOR HANDLE	Scratched	86.49 FL	*86.49 FL
12	1		*FRONT RH DOOR LOCK ASSY	Serviceable	746.35 FL	*- FL
13	1		*FRONT RH DOOR REGULATOR MOTOR	Serviceable	260.81 FL	*- FL
14	1		*FRONT RH DOOR INNER TRIM BOARD	Serviceable	1,085.15 FL	*- FL
15	1		*FRONT RH DOOR MOULDING	Serviceable	175.80 FL	*- FL
16	1		*FRONT RH DOOR WEATHERSTRIP	Serviceable	214.50 FL	*- FL
17	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
19 F=Fra	1 anchise p	part. S=SpcN	*SET SIDE SKIRT CLIP ett. L=ListItemDisc.	Not Necessary	50.00 FS	*-FS
	•			Sub Total (S\$)	9,670.28	3,299.26
			- List Item Discount on L	. Items 25.00/25.00% (S\$)	2,380.07	809.82
				Total Parts (S\$)	7,290.21	2,489.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	CHECK WIRING AND LIGHTNING SYSTEM	New	60.00	20.00
2	REMOVE & REFIT FRONT DOOR TRIMS & MECHANISM	New	200.00	60.00
3	REMOVE & REFIT REAR DOOR TRIMS & MECHANISM	New	200.00	60.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	500.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
		Gross Labour Cost (S\$)	3,410.00	1,070.00
	Report was unsubmit	ted during this print-out.		

< END OF ESTIMATES >