

## Invoice

To: Yong Fong Autogate Pte Ltd

Invoice No: 2020/INV/0132

CC: Sincerelead Garage Pte Ltd

Your Reference:

2 Buroh Crescent

Our Reference: 2020/0170

#02-09 ACE@Buroh

Date : 30/9/2020

Singapore 627546

| Description  | Amount S\$ |
|--|------------|
| <b>Particulars</b>   |            |
| Vehicle No: SLK5282U   |            |
| Accident Date : 2/9/2020   |            |
| Date of Inspection: 8/9/2020   |            |
| <b>Service:</b>  |            |
| Assessment with report<br>(inclusive of photographs and transport charges etc) | \$977      |
| Total Amount:  | \$977      |

Payment Details:

- 1) Cheque: Kindly make all cheques crossed and payable to **PRECISE APPRAISER PTE LTD**
- 2) Online Banking: **Maybank 041-9107653-9**



Precise Appraiser Pte Ltd

## Receipt

To: Yong Fong Autogate Pte Ltd

Invoice No: 2020/INV/0132

CC: Sincerelead Garage Pte Ltd

Your Reference:

2 Buroh Crescent

Our Reference: 2020/0170

#02-09 ACE@Buroh

Date : 30/9/2020

Singapore 627546

| Description  | Amount S\$ |
|--|------------|
| <b>Particulars</b>   |            |
| Vehicle No: SLK5282U   |            |
| Accident Date : 2/9/2020   |            |
| Date of Inspection: 8/9/2020   |            |
| <b>Service:</b>  |            |
| Assessment with report<br>(inclusive of photographs and transport charges etc) | \$977      |
| Total Amount:  | \$977      |

Payment Details:

- 1) Cheque: Kindly make all cheques crossed and payable to **PRECISE APPRAISER PTE LTD**
- 2) Online Banking: **Maybank 041-9107653-9**



Precise Appraiser Pte Ltd

To: Yong Fong Autogate Pte Ltd

CC: Sincerelead Garage Pte Ltd  
2 Buroh Crescent  
#02-09 ACE@Buroh  
Singapore 627546

### REFERENCES

|                     |               |                    |            |
|---------------------|---------------|--------------------|------------|
| Ref No              | : 2020/0170   | Date of Report     | : 3/9/2020 |
| Claim Type          | : Third Party | Date of Request    | : 8/9/2020 |
| Third party vehicle | : SLK5282U    | Date of Accident   | : 2/9/2020 |
| Insured Vehicle     | :             | Date of Inspection | : 8/9/2020 |
| Your Reference No   | : -           |                    |            |

### DAMAGED VEHICAL PARTICULARS

|                       |                     |                     |               |
|-----------------------|---------------------|---------------------|---------------|
| Registration Plate No | : SLK5282U          | Engine Modification | : NIL         |
| Model / Make          | : Honda Odyssey     | Pre-accident damage | : NIL         |
| Colour                | : Silver            | General Condition   | : Good        |
| Manufacturing Year    | : 2016              | General Paint Work  | : Good        |
| Engine No             | : K24W72012841      | Steering            | : Serviceable |
| Engine Capacity       | : 2400 cc           | Handbrake           | : Serviceable |
| Chassis No            | : JHMRC1880GC206718 | Footbrake           | : Serviceable |
| Odometer No           | : 109691            |                     |               |
| Transmission          | : Auto              |                     |               |

### TYRES CONDITION

|          |              |   |  |         |              |   |  |
|----------|--------------|---|--|---------|--------------|---|--|
| Front Lh |              |   |  | Rear Lh |              |   |  |
| Make     | : Giti       |   |  | Make    | : Giti       |   |  |
| Size     | : 215/55 r17 | 4 |  | Size    | : 215/55 r17 | 4 |  |
| Front Rh |              |   |  | Rear Rh |              |   |  |
| Make     | : Giti       |   |  | Make    | : Giti       |   |  |
| Size     | : 215/55 r17 | 4 |  | Size    | : 215/55 r17 | 4 |  |

The above millimetres represent the remaining life of tyre treads

### VEHICAL REPAIR COST

| <u>Descriptions</u>             | <u>Repairer (\$\$)</u> | <u>Difference (\$\$)</u> | <u>Adjuster (\$\$)</u> |
|---------------------------------|------------------------|--------------------------|------------------------|
| Parts                           | 12,541.86              |                          | 11,936.74              |
| Labour                          | 7,530.00               |                          | 6,400.00               |
| <b>Calculated Cost (\$\$) :</b> | <b>20,071.86</b>       | <b>1,735.12</b>          | <b>18,336.74</b>       |


|   |  |
|---|--|
| Recommended Lump Sum Repair Cost (\$\$) | : 14,650.00  |
| Estimate Repair Duration                | : 18   |
| Survey Inspection At                    | : Sincerelead Garage Pte Ltd                               |
| Survey Inspection Address               | : 2 Buroh Crescent<br>#02-09 ACE@Buroh<br>Singapore 627546 |

## DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear portion**.

Rear bumper, tailgate, rear both fender, rear end panel, spare tyre panel dented. Taillamp broken, rear windscreen shattered

Please see attached scheduled details.



## SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **18** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

Handwritten signature of Anthony and a circular blue stamp of Precise Appraiser Pte Ltd.

Anthony  
Automotive Appraiser  
MSAAA

## Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. *We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle.* All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2020/0170

Your Reference:

Vehicle Number : SLK5282U

| S/N          | Qty  | Description                            | Condition       | Repairer Estimate (\$\$) | Our Assessment (\$\$) |
|--------------|------|--|-----------------|--------------------------|-----------------------|
| <b>Parts</b> |      |  |                 |                          |                       |
| 1            | 1pcs | Rear bumper                            | Dented          | 752.50                   | 752.50                |
| 2            | 2pcs | Rear bumper side reflector @45.4/pcs   | Holder Torn     | 45.40                    | 45.40                 |
| 3            | 2pcs | Rear bumper side retainer @19.1/pcs    | Torn            | 19.10                    | 19.10                 |
| 4            | 2pcs | Taillamp @921.91/pcs                   | Grazed          | 1,843.82                 | 1,843.82              |
| 5            | 2pcs | Taillamp panel @184.38/pcs             | Dented          | 368.76                   | 368.76                |
| 6            | 2pcs | Taillamp lower garnish @99.84/pcs      | Deformed/ Torn  | 199.68                   | 199.68                |
| 7            | 1pcs | Tailgate                               | Dented          | 1,392.40                 | 1,392.40              |
| 8            | 1pcs | Tailgate logo                          | Necessary       | 36.82                    | 36.82                 |
| 9            | 1pcs | Tailgate chrome moulding               | Crack           | 245.00                   | 245.00                |
| 10           | 1pcs | Tailgate centre reflector              | Crack           | 322.56                   | 322.56                |
| 11           | 2pcs | Tailgate side reflector @540.68/pcs    | Broken          | 540.68                   | 540.68                |
| 12           | 1pcs | Tailgate inner lock                    | Dented          | 185.20                   | 185.20                |
| 13           | 1pcs | Tailgate inner rubber                  | Kinded          | 117.40                   | 117.40                |
| 14           | 2pcs | Tailgate absorber @164.5/pcs           | Bent            | 329.00                   | 329.00                |
| 15           | 1pcs | Tailgate inner handle                  | Deformed        | 23.38                    | 23.38                 |
| 16           | 1pcs | Tailgate inner trim                    | Deformed        | 309.45                   | 309.45                |
| 17           | 2pcs | Tailgate top side inner trim @41.8/pcs | Cut             | 83.60                    | 83.60                 |
| 18           | 1pcs | Tailgate top centre inner trim         | Cut             | 42.60                    | 42.60                 |
| 19           | 1pcs | Tailgate wiper arm                     | Grazed          | 42.60                    | 42.60                 |
| 20           | 1pcs | Tailgate wiper motor                   | Bent            | 350.42                   | 350.42                |
| 21           | 1pcs | Tailgate windscreen glass              | Shattered       | 1,237.56                 | 1,237.56              |
| 22           | 1pcs | Tailgate windscreen moulding           | Necessary       | 195.00                   | 195.00                |
| 23           | 1pcs | Rear end panel                         | Dented          | 552.96                   | 552.96                |
| 24           | 1pcs | Rear end panel inner trim              | Deformed        | 124.32                   | 124.32                |
| 25           | 1pcs | Spare tyre panel                       | Dented          | 473.06                   | 473.06                |
| 26           | 2pcs | Rear fender inner trim @833.43/pcs     | Holder Torn     | 1,666.86                 | 1,666.86              |
| 27           | 2pcs | Rear seat belt @368.9/pcs              | RH Bracket Bent | 737.80                   | 368.90                |
| 28           | 1pcs | Keyless antenna                        | Crack           | 298.00                   | 298.00                |
| 29           | 1pcs | Rear camera                            | Shorted         | 782.20                   | 782.20                |
| 30           | 1pcs | Rear a/c blower motor                  | Crack           | 521.70                   | 521.70                |

|                        |           |           |
|------------------------|-----------|-----------|
| <b>Total</b>           | 13,839.83 | 13,470.93 |
| <b>Less 20%</b>        | 2,767.97  | 2,694.19  |
| <b>Parts Sub Total</b> | 11,071.86 | 10,776.74 |

**Special Nett**

|    |      |                                   |           |        |        |
|----|------|-----------------------------------|-----------|--------|--------|
| 31 | 1set | Rear end panel sealant            | Necessary | 80.00  | 60.00  |
| 32 | 1set | Spare tyre panel sealant          | Necessary | 80.00  | 60.00  |
| 33 | 1set | Tailgate sealant                  | Necessary | 80.00  | 60.00  |
| 34 | 1pcs | Spare tyre insulator              | Necessary | 150.00 | 120.00 |
| 35 | 1set | Rear bumper clips                 | Necessary | 80.00  | 50.00  |
| 36 | 2set | Rear both fender inner trim clips | Necessary | 80.00  | 50.00  |
| 37 | 1set | Tailgate inner trim clips         | Necessary | 80.00  | 50.00  |
| 38 | 1pcs | Rear windscreen solar film        | Dislodge  | 300.00 | 250.00 |
| 39 | 1set | Rear windscreen sealant           | Necessary | 80.00  | 60.00  |
| 40 | 1set | Rear windscreen inner shield      | Necessary | 60.00  | 50.00  |
| 41 | 1pcs | Reverser sensor                   | Dented    | 400.00 | 350.00 |

|              |          |          |
|--------------|----------|----------|
| <b>Total</b> | 1,470.00 | 1,160.00 |
|--------------|----------|----------|

| Labour                       |  |           |           |
|------------------------------|--|-----------|-----------|
| 1                            | To check wiring system   | 80.00     | 50.00     |
| 2                            | To re-programme and reset after repair.  | 200.00    | 150.00    |
| 3                            | To r&r trimming and carpet for hot work repair.  | 300.00    | 200.00    |
| 4                            | To r&r rear air con and recharge air con gas.  | 200.00    | 150.00    |
| 5                            | To r&r rear windscreen glass.  | 150.00    | 120.00    |
| 6                            | To r&r rear exhaust for hot work repair.   | 150.00    | 100.00    |
| 7                            | To r&r fuel tank for replace of fuel tank.   | 150.00    | 100.00    |
| 8                            | To transfer tailgate attachments.  | 100.00    | 80.00     |
| 9                            | To cut and weld on rear end panel, spare tyre panel, tailamp panel. To panel beat on rear both fenders, rear chassis member, To r&r rear bumper, tailgate, taillamp and other attachments. | 4,000.00  | 3,500.00  |
| 10                           | To putty and respray rear bumper, tailgate, rear both fenders, rear end panel, spare tyre panel and accident affected area.  | 2,000.00  | 1,800.00  |
| 11                           | Rustproofing   | 200.00    | 150.00    |
| Labour Total                 |  | 7,530.00  | 6,400.00  |
| Sub Total (labour and parts) |  | 20,071.86 | 18,336.74 |

#### Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$14,650..**

Under normal circumstances, the repair period would be about **18** working days.