

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21011050/URA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	XE2480Z	Insured Vehicle No :	SHD2264B
Date of Loss:	08/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004396

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE2480Z	Engine No:	GH11739042
Make & Model:	UD TRUCKS CWB5ELPHNT, 10.8 D (M)	Chassis No:	JNCM1F1DXHU013470
Reg. Date:	05/12/2016 (Man. Year: 2016)	Odometer:	125381 km
Colour:	Yellow/Blue		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	KPATOS 7 mm	Rear Left Side:	KPATOS 7/7/7/7 mm
Front Right Side:	KPATOS 7 mm	Rear Right Side:	KPATOS 7/7/7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,817.20	8,764.20	12,053.00	57.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,950.00	2,050.00	51.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,817.20	10,714.20	14,103.00	56.83
Approved Total (Overridden) (S\$)		8,550.00		
Nett Amount (S\$)	24,817.20	8,550.00	16,267.20	65.55
+ Loss of Use (7.0 x S\$180.00/day) (S\$)		1,260.00		
Nett Liability (S\$)		9,810.00		

INSPECTION

Date of Assignment:	28/10/2021	Choo Motor Spray Painter (HQ)
Date Inspected:	28/10/2021 Inspected At:	1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Dec 2021)	
Parts:	N/A	UD TRUCKS CWB5ELPHNT 10.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE2480Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,320.00 F	*985.00 FL
2	1		*FRONT BUMPER SIDE N/S	Distorted	685.00 F	*655.00 FL
3	1		*FRONT BUMPER INNER BRACKET ASSY	Distorted	1,845.20 F	*1,100.00 FL
4	1		*FRONT BUMPER TOP STEP PROTECTOR N/S	Cut / Twisted	250.00 F	*245.00 FL
5	1		*REAR BUMPER FOG LAMP N/S	Cracked	185.00 F	*185.00 FL
6	1		*REAR BUMPER SIDE BLACK GARNISH N/S	Distorted	118.00 F	*118.00 FL
7	1		*HEADLAMP N/S	Cracked	1,450.00 F	*1,150.00 FL
8	1		*FRONT FOOT STEP N/S	Cracked	690.00 F	*690.00 FL
9	1		*FRONT FOOT STEP SIDE GARNISH N/S	Cracked	1,150.00 F	*1,120.00 FL
10	1		*FRONT FOOT STEP REFLECTOR N/S	Scratched	50.00 F	*40.00 FL
11	1		*FRONT FOOT STEP TOP SIDE GARNISH N/S	Cracked	1,280.00 F	*1,250.00 FL
12	1		*FRONT DOOR OUTER PILLAR N/S	Repair	1,109.00 F	*- FL
13	1		*FRONT DOOR N/S	Repair	3,220.00 F	*- FL
14	1		*OIL COOLER	Bent / Punctured	2,840.00 F	*2,200.00 FL
15	1		*OIL COOLER BRACKET	Repair	645.00 F	*- FL
16	1		*INTER COOLER	Serviceable	3,980.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	20,817.20	9,738.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	973.80
Total Parts (\$\$)	20,817.20	8,764.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	30.00
3	TO DISMANTLE & REPLACED OIL COOLER	New	250.00	100.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	900.00
5	TO PUTTY & SPRAY PAINTING	New	1,800.00	900.00
Gross Labour Cost (\$)			4,000.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >