

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21011053/R1vy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	03/11/2021		
	ATTN: ANG YVON	NE		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLF 178Y	Veh. Inspected	k	FBL 5828J	
	Policy No.	GA559734/1	Coverage (\$)		0.00	
	Claim No.	S1M03KQE	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		28/10/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA CBF190WH	c.c		184	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	LWBMC4691H1109004	Colour		RED	
	Odometer	56124 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	110/70-17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-17	MAXXIS		4 mm	
	L/H Rear Tyre				mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION.					
5.	5. General Information					
	Accident Date	24/10/2021	Inspect Date /	Time	28/10/2021 (05:14 PM)	
	Survey held at	ENG SOON PAINTING SVC				
	BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21011053/R1vy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser