

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21011058/APA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100484914
Claimant Vehicle No :	SMY2547R	Insured Vehicle No :	SGV2307D
Date of Loss:	24/10/2021	Nature of Claim:	TP
		Claim No:	7517680164SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY2547R	Engine No:	CZDC25686
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF30M1068685
Reg. Date:	25/02/2021 (Man. Year: 2020)	Odometer:	11679 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,115.00	7,760.64	4,354.36	35.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,432.00	4,132.00	3,300.00	44.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,547.00	11,892.64	7,654.36	39.16
+ GST 7.00/7.00% (S\$)	1,368.29	832.48	535.81	39.16
Nett Amount (S\$)	20,915.29	12,725.12	8,190.17	39.16
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,227.12		

INSPECTION

Date of Assignment:	28/10/2021		
Date Inspected:	29/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	59.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -RH (BLACK)	Not Necessary	110.00 FS	*- FS
4	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	383.00 FS	*- FS
6	1		*FRONT BUMPER AIR GRILLE -RH	Not Necessary	153.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	39.00 FS	*- FS
8	1		*FRONT FENDER -RH	Dented	1,286.00 FS	*1,028.80 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
10	1		*FRONT FENDER BRACE -RH	Not Necessary	88.00 FS	*- FS
11	1		*FRONT FENDER BRACKET -RH	Not Necessary	32.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER-RH (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
14	1		*FRONT FENDER COVER	Not Necessary	16.00 FS	*- FS
15	1		*HEADLIGHT MOUNTING -RH	Not Necessary	118.00 FS	*- FS
16	1		*HEADLIGHT -RH	Cut	5,589.00 FS	*4,471.20 FS
17	1		*HEADLIGHT LEFT CYLINDER -RH	Not Necessary	210.00 FS	*- FS
18	1		*HEADLIGHT LEFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
19	2		*FRONT WHEEL ARCH COVER-LH/RH	Not Necessary	536.00 FS	*428.80 FS
20	1		*FRONT DOOR LOWER COVER-RH	Not Necessary	268.00 FS	*- FS
21	1		*FRONT DOOR WINDOWS SLOT SEAL -RH	Not Necessary	224.00 FS	*- FS
22	1		*TYRE RIM -RH	Cut	1,262.00 FS	*1,009.60 FS
23	1		*SUNDRIES	Necessary	300.00 FS	*15.84 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					12,115.00	7,760.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY RHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER RHS FRONT FENDER AND RHS HEADLIGHT TO REPAIR RHS FRONT DOOR .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
5	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND RHS FRONT DOOR	New	3,000.00	1,650.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			7,432.00	4,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >