

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011063/ETY3N2**Date:** 23/11/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00094742102

Claimant Vehicle No : SMY9684G **Insured Vehicle No :** SJQ6269U

Date of Loss: 25/10/2021 Nature of Claim: TP Claim No: SNM21D206110/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY9684G**

Make & Model: MITSUBISHI OUTLANDER, 2.0 CVT SUNROOF (A) Engine No: 4J11DA1791

Reg. Date: 01/04/2021 (Man. Year: 2020) Chassis No: GF7W0701039

Colour: White Odometer: 5498 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18

Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,698.40	9,594.80	4,103.60	29.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	2,340.00	1,010.00	30.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,048.40	11,934.80	5,113.60	29.99
Approved Total (Overridden) (S\$)		9,550.00		
Nett Amount (S\$)	17,048.40	9,550.00	7,498.40	43.98

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 29/10/2021 Inspected At: YEW TEE JTC IND ESTATE
BLK 6 WOODLANDS RD 399J
REPAIRER: CAR PRO AUTO

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)**Parts:** M1-SUV MITSUBISHI OUTLANDER 2.0 CVT SUNROOF (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMY9684G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,020.00 FL	*1,020.00 FL
2	2		*REAR BUMPER LH & RH BRACKET	Bent	180.00 FL	*180.00 FL
3	1		*REAR BUMPER LOWER DIFFUSER GARNISH	Dented	395.00 FL	*360.00 FL
4	2		*REAR BUMPER REFLECTOR LAMP LH & RH	Broken	230.00 FL	*200.00 FL
5	2		*REAR BUMPER SIDE RETAINER LH & RH	Broken	155.00 FL	*155.00 FL
6	1		*SET REAR BUMPER FASTENERS	Necessary	38.00 FL	*30.00 FL
7	1		*TAILGATE	Dented	1,050.00 FL	*989.00 FL
8	1		*TAILGATE CENTER CHROME GARNISH	Broken	485.00 FL	*485.00 FL
9	1		*SET TAILGATE CENTER GARNISH FASTENERS	Necessary	32.00 FL	*10.00 FL
10	1		*TAILGATE LOCK ACURATOR	Bent	450.00 FL	*450.00 FL
11	1		*TAILGATE OUTLANDER EMBLEM	Necessary	95.00 FL	*95.00 FL
12	1		*TAILGATE LOGO EMBLEM	Necessary	80.00 FL	*80.00 FL
13	1		*TAILGATE C&C EMBLEM	Necessary	70.00 FL	*70.00 FL
14	1		*TAILGATE INNER TRIM BOARD	Broken	360.00 FL	*360.00 FL
15	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	38.00 FL	*15.00 FL
16	1		*TAILGATE WEATHERSTRIP	Crushed	295.00 FL	*213.00 FL
17	1		*TAILGATE INNER LOCK	Bent	435.00 FL	*435.00 FL
18	2		*TAILGATE LAMP LH & RH	Cut	820.00 FL	*820.00 FL
19	2		*TAILGATE ABSORBER LH & RH	Not Necessary	400.00 FL	*- FL
20	1		*TAILGATE WIPER ASSY	Not Necessary	450.00 FL	*- FL
21	2		*TAILGATE RUBBER STOPPER LH & RH	Not Necessary	60.00 FL	*- FL
22	1		*REAR WINDSCREEN	Not Necessary	980.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	165.00 FL	*165.00 FL
24	1		*TAILLAMP LH & RH ASSY	Cut	1,180.00 FL	*1,180.00 FL
25	2		*SET TAILLAMP ASSY FASTNERS LH & RH	Not Necessary	36.00 FL	*- FL
26	1		*REAR END PANEL	Dented	400.00 FL	*326.00 FL
27	1		*REAR END PANEL TOP GARNISH	Cut	190.00 FL	*113.00 FL
28	1		*SET REAR END PANEL TOP GARNISH FASTENERS	Necessary	22.00 FL	*15.00 FL
29	1		*REAR SPARE TYRE PANEL	Dented	1,300.00 FL	*751.00 FL
30	1		*REAR SPARE TYRE BOARD	Broken	320.00 FL	*320.00 FL
31	1		*REAR FENDER INNER TRIM BOARD LH & RH	O/s Broken	1,200.00 FL	*600.00 FL
32	2		*REAR FENDER INNER SHIELD LH & RH	Not Necessary	260.00 FL	*- FL
33	1		*REAR SPARE TYRE TOOLS BOX ASSY	Broken	255.00 FL	*255.00 FL
34	1		*EXHAUST MUFFLER	Dented	580.00 FL	*580.00 FL
35	2		*END PANEL AIR VENT BRACKET LH & RH	Not Necessary	150.00 FL	*- FL
36	1		*REAR NUMBER PLATE W CASING	Not Necessary	60.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
39	1		*SPARE TYRE PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
40	1		*REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
41	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
42	1		*REAR FLOOR PANEL INSULATION PAD	Necessary	150.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,116.00	10,622.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,417.60	1,027.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	13,698.40	9,594.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAYING OF AFFECTED AREAS	New	1,200.00	1,000.00
2	CARRY OUT BODY CAVITY PRESERVATION	New	150.00	30.00
3	TO REMOVE & REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING & REPOSITIONING REPLACEMENT PARTS & PANEL BEAT	New	1,000.00	900.00
4	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	CHECK WIRING	New	80.00	30.00
6	REMOVE/REFIX BOOT COMPARTMENT FITTINGS & ATTACHMENTS FOR	New	80.00	50.00
7	REMOVE & REFIX REVERSE CAMERA	New	100.00	30.00
8	REMOVE & REFIX REVERSE SENSOR	New	80.00	30.00
9	TO REMOVE & REFIX EXHAUST	New	100.00	50.00
10	TO REMOVE & REFIX TAILGATE COMPONENTS	New	80.00	50.00
11	REMOVE & REINSTALL REAR BOOT UPHOLSTERY & VACUUM NNER	New	80.00	50.00
12	TO STRAIGHTEN REAR CHASSIC MEMBER	New	250.00	0.00
Gross Labour Cost (\$\$)			3,350.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >