

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1888M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH	DEFORMED	588.80	588.80
1	FRT FENDER BLUE-DRIVE LH	NECESSARY	26.60	26.60
1	FRT FENDER SHIELD LH	SERVICEABLE	164.70	-
1	FRT WHEEL CAP LH	SCRATCHED	346.40	346.40
1	WING MIRROR LH	CUT	1,391.70	1,391.70
1	FRT BUMPER	CUT	430.90	430.90
10	FRT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NECESSARY	35.00	35.00
1	HEADLAMP LH	SCRATCHED	1,993.65	1,993.65
1	RADIATOR GRILLE	SCRATCHED	1,568.60	1,568.60
	LESS 20% DISCOUNT		-1,313.67	-1,280.73
			5,254.68	5,122.92
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	CHECK WIRINGS/LIGHTINGS.		40.00	20.00
	TUFF KOTE.		60.00	30.00
			1,800.00	1,250.00
	GRAND TOTAL		7,054.68	6,372.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,900.00

Report Ref No. NS/INC21011067/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.