

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC21011067/\	/vcn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				05-11-2021		
			Code:	INC4		
1.	,					
	Insured Veh.	SGR 4892M		nspected	SHC 1888M	
	Policy No.		<b>-</b>	age (\$)	0.00	
	Claim No.	MT/1148151-002	Exces		0.00	
	Assign From		Assig	n Date	18/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ ELECTRIC	c.c		0	
	Engine No.	HIDDEN	Year c	f Reg.	2018	
	Chassis No.	KMHC851HUJU021909	Colou	r	BLUE	
	Odometer	-	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/10/2021	Insped	tion Date	18/10/2021	
	Survey held at	ey held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				