

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC21011068/Vucn2		
73 BRAS BASAH ROAD						
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	03-11-2021		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMJ 316H	Veh. Ir	spected	SHB 2311J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1149640-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	18/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093540	Coloui	•	YELLOW	
	Odometer	574246	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	206/60 R16	WEST	_AKE	5 mm	
	L/H Front Tyre	206/60 R16	WEST LAKE		5 mm	
	R/H Rear Tyre	206/60 R16	WEST LAKE		5 mm	
	L/H Rear Tyre	206/60 R16	WEST	_AKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/10/2021	Inspection Date 18/10/2021			
	Survey held at	vey held at COMFORTDELGRO ENGINEERING PTE LTD				
	59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					