



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7967D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-FR BUMPER	DENTED	430.90	430.90
10	BUMPER COVER CLIP FRONT	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-90.58	-90.58
			362.32	362.32
LABOUR				
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
			700.00	600.00
GRAND TOTAL			1,062.32	962.32
RECOMMENDED COST OF REPAIRS (CONFIRMED)				962.32

Report Ref No. NS/INC21011069/Vqce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.