

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011076/AQY3N2**Date:** 27/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00094242100

**Claimant Vehicle
No :** GBK8947J**Insured Vehicle
No :** SMQ4171U

Date of Loss: 27/10/2021

Nature of Claim: TP

Claim
No: SNM21D206173/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBK8947J**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Engine No: 1KDB063692

Reg. Date: 04/01/2021 (Man. Year: 2020)

Chassis No: JTFAT35Y90K215948

Colour: White

Odometer: 38875 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15

Rear Tyre Size: 155R12C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,093.10	2,376.02	4,717.08	66.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,250.00	950.00	43.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,293.10	3,626.02	5,667.08	60.98
Approved Total (Overridden) (\$\$)		2,900.00		
(\$\$)	9,293.10	2,900.00	6,393.10	68.79
+ GST 7.00/7.00% (\$\$)	650.52	203.00	447.52	68.79
Nett Amount (\$\$)	9,943.62	3,103.00	6,840.62	68.79

INSPECTION

Date of Assignment: 29/10/2021

Date Inspected: 02/11/2021 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 May 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK8947J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH OUTER RIM	Cut	224.70 FL	*224.70 FL
2	1		*REAR LH FENDER (FRONT)	Dented	355.00 FL	*355.00 FL
3	1		*REAR LH FENDER (REAR)	Dented	355.00 FL	*355.00 FL
4	1		*REAR LH MUDFLAP	Not Necessary	75.80 FL	*- FL
5	1		*REAR LH WHEEL BEARING	Damaged	2,681.50 FL	*420.00 FL
6	1		*REAR LH WHEEL BEARING SHAFT	Not Necessary	698.80 FL	*- FL
7	1		*FRONT LH ALUMINIUM CENTER ALUMINIUM	Dented	800.00 FS	*480.00 FS
8	1		*FRONT LH ALUMINIUM COMPOSITE PAD COVER	Repair	400.00 FS	*- FS
9	1		*LH SIDE STEP BRACKET ASSY	Bent	600.00 FS	*480.00 FS
10	1		*LH SIDE SWING DOOR RUBBER SEAL ASSY	Cut	900.00 FS	*400.00 FS
11	1		*REAR LH ALUMINIUM COMPOSITE PAD COVER	Not Necessary	600.00 FS	*- FS
12	1		*REAR LH CENTER TYRE	Not Necessary	200.00 FS	*- FS
13	1		*SIKA GLUE	Not Necessary	200.00 FS	*- FS
14	1		*SILICONE KIT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,190.80	2,714.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,097.70	338.68
Total Parts (\$\$)	7,093.10	2,376.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART. (TO FR)	New	200.00	120.00
2	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.	New	100.00	80.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,000.00	600.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	900.00	450.00
Gross Labour Cost (\$)			2,200.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >