

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011078/KVY3N2**Date:** 23/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00117192000
<b>Claimant Vehicle No :</b>	GBG6899Z	<b>Insured Vehicle No :</b>	XD6223D
Date of Loss:	21/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D206060/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBG6899Z</b>	Engine No:	K9KC400D057192
Make & Model:	NISSAN NV200, 1.6 (A)	Chassis No:	VSKYBAM20Z0145668
Reg. Date:	29/09/2017 (Man. Year: 2017)	Odometer:	34241 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,513.40	1,997.85	2,515.55	55.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,250.00	1,450.00	53.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,213.40</b>	<b>3,247.85</b>	<b>3,965.55</b>	<b>54.97</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	7,213.40	2,600.00	4,613.40	63.96
<b>+ GST 7.00/7.00% (S\$)</b>	504.94	182.00	322.94	63.96
<b>Nett Amount (S\$)</b>	<b>7,718.34</b>	<b>2,782.00</b>	<b>4,936.34</b>	<b>63.96</b>

**INSPECTION**

Date of Assignment:	29/10/2021	
Date Inspected:	29/10/2021	Inspected At: Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Nov 2021)	
<b>Parts:</b>	N/A	NISSAN NV200 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG6899Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LHS	Bent	1,640.00 FL	*1,636.00 FL
2	1		*REAR FENDER INNER SHIELD LHS	Serviceable	200.00 FL	*- FL
3	1		*REAR FENDER MOULDING LHS	Dented/Cut	200.00 FL	*95.40 FL
4	1		*REAR BUMPER	Serviceable	490.00 FL	*- FL
5	1		*REAR BUMPER RETAINER LHS	Serviceable	40.00 FL	*- FL
6	1		*REAR BUMPER SPONGE	Serviceable	100.00 FL	*- FL
7	1		*TAIL LAMP LHS	Broken	250.00 FL	*250.00 FL
8	1		*TAIL GATE DOOR LHS	Repair	1,220.00 FL	*- FL
9	1		*TAIL GATE DOOR UPPER HINGE	Repair	108.00 FL	*- FL
10	1		*TAIL GATE DOOR LOWER HINGE	Repair	108.00 FL	*- FL
11	1		*END PANEL OUTER	Repair	260.00 FL	*- FL
12	1		*NV200 EMBLEM	Necessary	150.00 FL	*145.20 FL
13	1		*NISSAN EMBLEM	Necessary	160.00 FL	*79.90 FL
14	1		*70KM/HR STICKER	Necessary	20.00 FS	*12.00 FS
15	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,006.00</b>	<b>2,218.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	492.60	220.65
<b>Total Parts (\$\$)</b>	<b>4,513.40</b>	<b>1,997.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	700.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,200.00	500.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	30.00
5	ALIGNMENT CHECK	New	100.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,700.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >