

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011083/GVY3Q2**Date:** 11/08/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00123102003		
Claimant Vehicle No :	SMH2028L	Insured Vehicle No :	GBG9729L		
Date of Loss:	28/10/2021	Nature of Claim:	TP	Claim No:	SNM21D206196/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2028L	Engine No:	2ZR0B22496
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800309771
Reg. Date:	15/01/2019 (Man. Year: 2018)	Odometer:	25969 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,429.19	10,535.46	2,893.73	21.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,520.00	810.00	24.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,759.19	13,055.46	3,703.73	22.10
+ GST 7.00/7.00% (S\$)	1,173.14	913.88	259.26	22.10
Nett Amount (S\$)	17,932.33	13,969.34	3,962.99	22.10

INSPECTION

Date of Assignment:	29/10/2021		
Date Inspected:	29/10/2021	Inspected At:	Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	10.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Aug 2022)**Parts:** M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMH2028L)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,812.00 FL	*1,812.00 FL
2	1		*REAR TAILGATE GLASS	Smashed	1,297.80 FL	*1,297.80 FL
3	1		*REAR TAILGATE GLASS MOULDING	Necessary	164.70 FL	*135.00 FL
4	1		*REAR TAILGATE EMBLEM	Necessary	66.78 FL	*66.78 FL
5	1		*REAR TAILGATE OUTER CHROME MOULDING	Cracked	907.80 FL	*581.00 FL
6	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	57.90 FL	*49.80 FL
7	1		*REAR TAILGATE NO PLATE LIGHT	Cracked	91.90 FL	*91.90 FL
8	1		*REAR TAILGATE THIRD BRAKE LIGHT	Cracked	195.70 FL	*195.70 FL
9	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	827.40 FL	*- FL
10	1		*REAR TAILGATE WIPER ARM	Not Necessary	67.50 FL	*- FL
11	1		*REAR TAILGATE WIPER BLADE	Not Necessary	35.10 FL	*- FL
12	1		*REAR TAILGATE INNER TRIMBOARD	Deformed	673.00 FL	*605.10 FL
13	1		*REAR TAILGATE TRIM COVER -TOP	Cracked	231.40 FL	*204.50 FL
14	1		*REAR TAILGATE TRIM COVER -RH	Cracked	28.50 FL	*28.50 FL
15	1		*REAR TAILGATE PULL HANDLE COVER	Not Necessary	33.50 FL	*- FL
16	1		*REAR TAILGATE INNER LOCK	Bent	467.00 FL	*467.00 FL
17	1		*REAR TAILGATE RUBBER	Twisted	372.30 FL	*372.30 FL
18	1		*REAR RH TAILLAMP	Cracked	732.60 FL	*732.60 FL
19	1		*REAR LH TAILLAMP	Cracked	732.60 FL	*732.60 FL
20	1		*REAR RH CORNER COVER	Not Necessary	229.60 FL	*- FL
21	1		*REAR LH CORNER COVER	Deformed	229.60 FL	*229.60 FL
22	1		*REAR RH CORNER COVER RETAINER	Not Necessary	160.70 FL	*- FL
23	1		*REAR LH CORNER COVER RETAINER	Deformed	160.70 FL	*75.60 FL
24	1		*REAR BUMPER	Deformed	750.90 FL	*750.90 FL
25	1		*REAR BUMPER RH REFLECTOR	Not Necessary	82.30 FL	*- FL
26	1		*REAR BUMPER LH REFLECTOR	Cut	82.30 FL	*82.30 FL
27	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	159.90 FL	*- FL
28	1		*REAR BUMPER LH SIDE RETAINER	Deformed	159.90 FL	*120.00 FL
29	1		*REAR END PANEL	Buckled	735.70 FL	*735.70 FL
30	1		*REAR END PANEL TOP TRIM	Deformed	233.10 FL	*204.50 FL
31	1		*REAR SPARE TYRE PANEL	Repair	781.70 FL	*- FL
32	1		*REAR SPARE TYRE PANEL TOP COVER	Bent	1,105.50 FL	*845.00 FL
33	1		*REAR SPARE TYRE PANEL INSULATOR	Torn	455.20 FL	*427.70 FL
34	1		*REAR TOOL BOX	Torn	491.60 FL	*491.60 FL
35	1		*REAR RH FENDER INNER TRIMBOARD	Deformed	741.80 FL	*612.00 FL
36	1		*REAR LH FENDER INNER TRIMBOARD	Deformed	741.80 FL	*612.00 FL
37	20		*REAR FENDER INNER TRIMBOARD CLIPS	Necessary	70.00 FL	*30.00 FL
38	1		*REAR TAILGATE REVERSE CAMERA	Damaged	380.00 FS	*250.00 FS
39	1		*REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS
40	1		*REAR WINDSCREEN GLASS GUM	Necessary	60.00 FS	*60.00 FS
41	1		*REAR NO PLATE	Bent	40.00 FS	*40.00 FS
42	1		*REAR KEYLESS SENSOR	Broken	117.10 FL	*117.10 FL
43	1		*REAR LH FENDER AIR VENT	Deformed	135.87 FL	*135.87 FL
44	1		*REAR LH FENDER SIDE PROTECTOR	Broken	471.50 FL	*471.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,652.25 13,863.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	280.00	0.00
3	TO REPAIR DAMAGES	New	1,600.00	1,200.00
4	TO SPRAY PAINTING	New	1,300.00	1,200.00
Gross Labour Cost (\$\$)			3,330.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >