

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011085/KGA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800112995
Claimant Vehicle No :	SLV6640E	Insured Vehicle No :	SMF8666R
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	1819060059SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6640E	Engine No:	L15B5460170
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81200137
Reg. Date:	09/01/2018 (Man. Year: 2017)	Odometer:	128690 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Arivo 8 mm	Rear Left Side:	Arivo 8 mm
Front Right Side:	Arivo 8 mm	Rear Right Side:	Arivo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,136.72	1,050.48	9,086.24	89.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	835.00	2,035.00	70.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,006.72	1,885.48	11,121.24	85.50
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	13,006.72	1,500.00	11,506.72	88.47
+ GST 7.00/7.00% (S\$)	910.47	105.00	805.47	88.47
Nett Amount (S\$)	13,917.19	1,605.00	12,312.19	88.47
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,928.00		

INSPECTION

Date of Assignment:	29/10/2021	
Date Inspected:	05/04/2022	Inspected At: KBS MOTORSPORTS PTE LTD (HQ) 160 Sin Ming Drive, #06-03 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	184.70 FL	*74.10 FL
2	1		*REAR WINDSCREEN	Serviceable	1,082.60 FL	*- FL
3	1		*TAILGATE	Bent	1,351.20 FL	*1,092.00 FL
4	1		*TAILGATE LOCK	Repair	498.60 FL	*- FL
5	1		*TAILGATE STRIKER	Repair	118.90 FL	*- FL
6	1		*TAILGATE CHROME TRIM	Serviceable	566.30 FL	*- FL
7	1		*TAILGATE WEATHER SEAL	Serviceable	187.50 FL	*- FL
8	1		*TAILGATE EMBLEM SHUTTLE	Necessary	110.90 FL	*72.00 FL
9	1		*TAILGATE EMBLEM HYBRID	Not Necessary	105.60 FL	*- FL
10	1		*TAILGATE EMBLEM HONDA	Necessary	102.80 FL	*75.00 FL
11	1		*TAILGATE INNER TRIM BOARD	Serviceable	787.20 FL	*- FL
12	1		*TAILGATE LAMP LH	Serviceable	846.80 FL	*- FL
13	1		*TAILGATE LAMP RH	Serviceable	846.80 FL	*- FL
14	1		*BRAKE LAMP LH	Serviceable	995.10 FL	*- FL
15	1		*BRAKE LAMP RH	Serviceable	995.10 FL	*- FL
16	1		*REAR BUMPER	Repair	1,089.90 FL	*- FL
17	1		*REAR BUMPER RETAINER LH	Serviceable	102.50 FL	*- FL
18	1		*REAR BUMPER RETAINER RH	Serviceable	102.50 FL	*- FL
19	1		*REAR BUMPER SIDE GRILLE LH	Serviceable	146.90 FL	*- FL
20	1		*REAR BUMPER SIDE GRILLE RH	Serviceable	146.90 FL	*- FL
21	1		*REAR BUMPER REFLECTOR LH	Serviceable	97.30 FL	*- FL
22	1		*REAR BUMPER REFLECTOR RH	Serviceable	97.30 FL	*- FL
23	1		*END PANEL TOP GARNISH	Serviceable	198.40 FL	*- FL
24	1		*END PANEL	Repair	984.10 FL	*- FL
25	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*REAR NUMBER PLATE +HOLDER	Serviceable	60.00 FS	*- FS
27	10		*REAR BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
28	2		*REAR BUMPER REVERSE SENSOR	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,485.90	1,313.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,349.18	262.62
Total Parts (\$\$)	10,136.72	1,050.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,200.00	200.00
2	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	New	50.00	0.00
3	TO REMOVE & INSTALL REAR BOOT LID COMPONENT TO FACILITATE REPAIR	New	80.00	60.00
4	TO REMOVE & REPLACE REAR WINDSCREEN	New	120.00	120.00
5	TO REMOVE & REPLACE BUMPER SENSORS	New	120.00	0.00
6	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	250.00	0.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	50.00	15.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	440.00
Gross Labour Cost (\$)			2,870.00	835.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >