

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011086/R1GS3Q2**Date:** 10/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKV5642T	Insured Vehicle No :	SLL6049R
Date of Loss:	24/10/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004639

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV5642T	Engine No:	CJZ619417
Make & Model:	VOLKSWAGEN GOLF, 1.2 TSI (A)	Chassis No:	WVWZZZAUZFW352050
Reg. Date:	23/09/2015 (Man. Year: 2015)	Odometer:	67675 km
Colour:	Blue		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,254.39	1,964.14	2,290.25	53.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,840.00	4,040.00	5,800.00	58.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,094.39	6,004.14	8,090.25	57.40
+ GST 7.00/7.00% (S\$)	986.61	420.29	566.32	57.40

Nett Amount (S\$)	15,081.00	6,424.43	8,656.57	57.40
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,631.88		

INSPECTION

Date of Assignment: 29/10/2021

Date Inspected: 01/11/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2021)
Parts: 144	VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKV5642T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -GOLF	Necessary	80.51 FS	*80.51 FS
2	1		*INSCRIPTION PURE WHITE /PO NAME PLATE -BLUEMOTION	Necessary	83.51 FS	*83.51 FS
3	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -TSI	Necessary	75.19 FS	*75.19 FS
4	1		*COVER FOR BUMPER PRIMED	Deformed	1,307.28 FS	*1,307.28 FS
5	1		*REAR DIFFUSOR SATIN BLACK	Scratched	337.65 FS	*337.65 FS
6	1		*BUMPER REINFORCEMENT	Serviceable	652.80 FS	*- FS
7	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Serviceable	70.26 FS	*- FS
8	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Serviceable	40.70 FS	*- FS
9	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Serviceable	40.70 FS	*- FS
10	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Serviceable	40.70 FS	*- FS
11	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Serviceable	40.70 FS	*- FS
12	2		*LICENSE PLATE LIGHT	Serviceable	81.94 FS	*- FS
13	1		*END PLATE END PANEL OUTER	Serviceable	186.94 FS	*- FS
14	1		*ZINC SPRAY	Not Necessary	69.13 FS	*- FS
15	1		*2K-BODY ADHESIVE	Not Necessary	445.77 FS	*- FS
16	1		*SEALANT CAN BE SPRAYED	Not Necessary	64.55 FS	*- FS
17	6		*WELD STUD	Not Necessary	6.06 FS	*- FS
18	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
19	1		*REAR WATER LEAK TEST	Not Necessary	150.00 FS	*- FS
20	1		*REVERSE SENSOR	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	4,254.39	1,964.14
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	1,680.00
4	SPRAY PAINT	New	3,200.00	1,600.00
5	R&R REAR LUGGAGE TRIM	New	840.00	0.00
			Gross Labour Cost (S\$)	9,840.00
				4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >