



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21011091/Kqf3q2 Date: 01/04/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMA 3201H	Veh. Inspected	SMT 1016P	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012238/CD	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	29/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 216D (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBA2B320X0V926388	Colour	METALLIC GREY	
Odometer	70163 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	3 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	3 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/10/2021	Inspection Date	01/11/2021	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	