6/2/22, 12:01 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21011095/KPA3Q2

Date: 02/06/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210003373

Claimant Vehicle

No: EK666L Insured Vehicle No: GR1228B

Date of Loss: 29/10/2021 Nature of Claim: TP Claim No: 6199651209SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EK666L**

 Make & Model:
 TOYOTA ALPHARD, 2.5 SC CVT (A)
 Engine No:
 2AR2298999

 Reg. Date:
 13/01/2020 (Man. Year: 2019)
 Chassis No:
 AGH300284875

 Colour:
 Metallic Pearl White
 Odometer:
 27996 km

Engine Capacity: 2493 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,926.30	4,404.85	3,521.45	44.43
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,045.00	1,750.00	295.00	14.43
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,971.30	6,154.85	3,816.45	38.27
	Approved Total (Overridden) (S\$)	4,900.00			
	(S\$)	9,971.30	4,900.00	5,071.30	50.86
	+ GST 7.00/7.00% (S\$)	697.99	343.00	354.99	50.86
	Nett Amount (S\$)	10,669.29	5,243.00	5,426.29	50.86
	+ Car Rental (11.0 x S\$1	150.00/day) (S\$)	1,650.00		
	+ Doc/s	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	6,900.45		
	Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 29/10/2021

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 01/11/2021 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
	1	*LH REAR DOOR	Bent	2,856.80 F	*1,872.60 FI
2	1	*LH REAR DOOR WINDOW REGULATOR	Distorted	275.90 F	*275.90 FI
3	1	*LH REAR DOOR LOWER MOULDING	Mtg Cracked	752.40 F	*752.40 F
Ļ	1	*LH REAR FENDER	Bent	1,521.60 F	*1,521.60 FI
5	1	*LH REAR FENDER WHEEL COWLING	Cracked	271.40 F	*271.40 FI
6	1	*SET LH REAR FENDER WHEEL COWLING CLIPS	Necessary	48.00 F	*48.00 F
7	1	*SET LH REAR FENDER FRONT LOWER GARNISH	Serviceable	298.60 F	*- FI
3	1	*LH REAR FENDER WINDOW GLASS MOULDING	Necessary	895.70 F	*123.00 FI
)	1	*REAR BUMPER	Buckled / Distorted	780.50 F	*780.50 F
10	1	*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 F
11	1	*LH REAR BUMPER RETAINER	Distorted	103.40 F	*103.40 F
12	1	*LH REAR FENDER WINDOW GLASS SEALANT	Necessary	60.00 FS	*40.00 F
3 ==Fra	1 anchise	*LH REAR FENDER WINDOW GLASS INNER RUBBER SEAL part. S=SpcNett. L=ListItemDisc.	Necessary	27.00 FS	*27.00 F
		part o operiou i i incominatori	Sub Total (S\$)	7,926.30	5,850.80
- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	1,445.95
			Total Parts (S\$)	7,926.30	4,404.85

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND REINSTALL LH REAR FENDER WINDOW GLASS AND CONDUCT WATER LEAK TEST	New	100.00	80.00
2	TO REMOVE AND INSTALL CENTRE SEATS ,REAR SEATS ,LH REAR FENDER INNER TRIM ,FLOOR CARPET TO FACILITATE REPAIRS ON LH REAR FENDER	New	120.00	100.00
3	TO REMOVE DAMAGED PARTS ,TO JACK OUT LH REAR FENDER INNER PANEL ,LH FRONT DOOR PILLAR,LH RUNNING BOARD PANEL,AND CUT OUT DAMAGED PANELS ,TO REWELD ,RESHAPE AND REPAIR LH REAR FENDER AND INNER PANEL,LH CENTRE DOOR PILLAR ,TO REMOVE AND REFIT DOOR TRIM LOCK ,WINDOW ,TO REPLACE DAMAGED PARTS AND ADJUST BODY PANEL ALIGNMENT	New	850.00	750.00
4	TO SPRAY PAINT AFFECTED LH REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL (PEARL PAINT)	New	950.00	800.00
5	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	25.00	20.00
	Gross Labou	r Cost (S\$)	2,045.00	1,750.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >