

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011105/VEA3Q2**Date:** 28/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070058642
<b>Claimant Vehicle No :</b>	SHB8811T	<b>Insured Vehicle No :</b>	SFH6522H
Date of Loss:	29/10/2021	Nature of Claim:	TP
		Claim No:	1227735442SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB8811T</b>		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEJU156318
Reg. Date:	09/05/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU129685
Colour:	Silver	Odometer:	281904 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,533.36	1,786.88	2,746.48	60.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,370.00	870.00	38.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,773.36</b>	<b>3,156.88</b>	<b>3,616.48</b>	<b>53.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	474.14	220.98	253.16	53.39
<b>Nett Amount (S\$)</b>	<b>7,247.50</b>	<b>3,377.86</b>	<b>3,869.64</b>	<b>53.39</b>
<b>+ Car Rental (4.0 x S\$72.76/day) (S\$)</b>		291.04		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,670.90</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,670.00</b>		

INSPECTION

Date of Assignment:	29/10/2021	
Date Inspected:	29/10/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	4.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,480.40 FL	*- FL
2	1		*EMBLEM HYUNDAI	Necessary	28.00 FL	*28.00 FL
3	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
4	1		*EMBLEM LONIQ	Necessary	31.30 FL	*31.30 FL
5	2		*REAR N/S & O/S TAIL LAMPS	Serviceable	725.20 FL	*- FL
6	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	294.80 FL	*294.80 FL
8	2		*REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	Serviceable	20.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	Serviceable	15.00 FL	*- FL
10	2		*REAR BUMPER N/S & O/S STAY	Cut	276.20 FL	*276.20 FL
11	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	66.20 FL	*- FL
12	1		*REAR BUMPER LOWER MOULDING CENTRE	Scratched	216.50 FL	*216.50 FL
13	1		*REAR BUMPER LOWER COVER	Distorted	47.50 FL	*47.50 FL
14	1		*REAR BUMPER CAP HOOK	Cut	9.10 FL	*9.10 FL
15	1		*REAR BUMPER N/S & O/S REFLECTOR	Serviceable	63.80 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
17	1		*SET REVERSE SENSOR	Cut	280.00 FS	*280.00 FS
18	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
19	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
20	1		*SUNDRY	Serviceable	50.00 FS	*- FS
21	1		*LAMP ASSY (REAR FOG)	Broken	201.50 FL	*201.50 FL
22	1		*REAR BUMPER LIP	Cut	47.50 FL	*47.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,534.70</b>	<b>2,114.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,001.34	327.22
<b>Total Parts (\$\$)</b>	<b>4,533.36</b>	<b>1,786.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE /REFIT REAR TAILGATE WINDOW GLASS ONTO NEW TAILGATE	New	120.00	0.00
3	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
4	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	40.00
5	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE END PANEL ETC	New	850.00	540.00
6	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL ,REAR BUMPER LOWER COVER (BLACK) ,TAILGATE	New	800.00	720.00
7	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,240.00</b>	<b>1,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >