

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21011106/BQF3N2**Date:** 08/03/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/21-513972-WTT
Claimant Vehicle No :	SKF8517L	Insured Vehicle No :	FBH956B
Date of Loss:	28/10/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF8517L		
Make & Model:	MERCEDES-BENZ C180, 1.8 (A)	Engine No:	27182030223556
Reg. Date:	11/07/2012 (Man. Year: 2011)	Chassis No:	WDD2040492A537598
Colour:	Silver	Odometer:	212151 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	255/35R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,325.93	3,717.97	7,607.96	67.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	940.00	3,120.00	76.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,385.93	4,657.97	10,727.96	69.73
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	15,385.93	3,700.00	11,685.93	75.95
+ GST 7.00/7.00% (S\$)	1,077.02	259.00	818.02	75.95
Nett Amount (S\$)	16,462.95	3,959.00	12,503.95	75.95

INSPECTION

Date of Assignment:	29/10/2021		
Date Inspected:	01/11/2021	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF8517L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH	Not Damaged	920.00 FL	*- FL
2	1		*REAR TAIL LAMP SIDE GARNISH RH	Not Damaged	150.00 FL	*- FL
3	1		*REAR BUMPER	Broken	1,578.66 FL	*1,221.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Damaged	680.00 FL	*- FL
5	1		*REAR BUMPER SPONGE	Not Damaged	138.00 FL	*- FL
6	1		*REAR BUMPER INNER REINFORCEMENT PLASTIC	Not Damaged	320.00 FL	*- FL
7	1		*REAR BUMPER TOWING COVER	Missing	120.00 FL	*42.00 FL
8	1		*REAR BUMPER LOWER LID	Broken	680.00 FL	*462.54 FL
9	1		*REAR BUMPER SIDE RETAINERS LH	Necessary	80.00 FL	*48.90 FL
10	1		*REAR BUMPER SIDE RETAINERS RH	Necessary	80.00 FL	*48.90 FL
11	1		*REAR BUMPER LOWER BRACKET LH	Necessary	238.00 FL	*65.00 FL
12	1		*REAR BUMPER LOWER BRACKET RH	Necessary	238.00 FL	*65.00 FL
13	1		*BOOT LID	Bent	1,758.60 FL	*1,758.60 FL
14	1		*BOOT LID EMBLEM LOGO	Necessary	98.00 FL	*59.80 FL
15	1		*BOOT LID EMBLEM C180	Necessary	125.00 FL	*76.00 FL
16	1		*BOOT LID INNER LOCK	Not Damaged	413.00 FL	*- FL
17	1		*BOOT LID LOCK CATCH	Not Damaged	178.00 FL	*- FL
18	1		*BOOT LID WEATHERSTRIP	Not Damaged	298.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Damaged	238.00 FL	*- FL
20	1		*REAR BUMPER INNER SIDE GARNISH LH	Not Damaged	238.00 FL	*- FL
21	1		*REAR BUMPER INNER SIDE GARNISH RH	Not Damaged	238.00 FL	*- FL
22	1		*REAR END PANEL OUTER	Not Damaged	870.00 FL	*- FL
23	1		*REAR END PANEL INNER GARNISH	Not Damaged	316.00 FL	*- FL
24	1		*SET REVERSE SENSOR	Short Circuit	1,200.00 FL	*250.00 FL
25	1		*SPARE TYRE PANEL	Not Damaged	1,080.00 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*TAIL LAMP SIDE GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
28	1		*REAR END PANEL INNER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,553.26	4,127.74
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,227.33	409.77
Total Parts (\$\$)	11,325.93	3,717.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	1,800.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREA	New	1,600.00	400.00
3	CHECK AND REPAIR WIRING SYSTEM	New	120.00	0.00
4	RNR REAR REVERSE SENSOR AND RESETTNG SYSTEM	New	300.00	60.00
5	RESPRAY TUFF COAT ON ACCIDENT AREA	New	120.00	0.00
6	RNR BOOT LID INNER FITTINGS	New	120.00	80.00
Gross Labour Cost (\$)			4,060.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >