

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011110/T1VF3Q2
Date: 26/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900018031
Claimant Vehicle No :	GBC2810B	Insured Vehicle No :	SDV1888K
Date of Loss:	26/10/2021	Nature of Claim:	TP
		Claim No:	8322197545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2810B	Engine No:	1KD2125013
Make & Model:	TOYOTA HIACE, 3.0 D MANUAL (M)	Chassis No:	JTFHT02P900082130
Reg. Date:	18/10/2011 (Man. Year: 2011)	Odometer:	435375 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/26/21, 2:07 PM

Adjuster Report

Date of Assignment: 01/11/2021

Date Inspected: 01/11/2021

Inspected At:

Song Hin Motor (HQ)
BLK 15 DEFU LANE 10 #01-386
Singapore 1953

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$38,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	4		*REAR BUMPER LOWER BRACKET	Bent	0.00 F	*- F
4	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
5	1		*REAR END PANEL	Bent	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Bent	0.00 F	*- F
7	1		*TAILGATE	Bent	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*TAILGATE LOCK	Bent	0.00 F	*- F
12	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
13	1		*SPARE TYRE BRACKET	Repair	0.00 F	*- F
14	1		*FLOOR PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >