

TP AXA.

Denise

JS1K4363 . 2017 Oct.

Yamaha 135LC 134cc

PMYU60420H0109725

Front Fender.	lt	95	✓
Front wheel Rim.	new	280(SW)	+
Front Fork Assy.	2	480.	+
Front Fork underbracket.	MP	185.	+
Front Fork Oil	new	30(SW)	✓
Steering Core and Bearing.	new	75	✓
Front Wing Mirror x02	Missing	48x2=96	✓
Headlamp	XL new	185	+
Headlamp Cowling.	Cowled	105	✓
Front Cowling.	lt	125	✓
Front Cowling Logo.	new	20	✓
Front LH Signal Lamp.	new	80x2=160	+

JSK 4363

Front LH Side Fairing	✓	110.	✓
Balancer LH.	✓	25	✓
Front Basket.	XHP Dec	50(SN)	X
IU unit	✓	165(SN)	✓
Front LH Footrest Rubber	✓	35	✓
Front Footrest Bracket	✓	65	✓
Rear Footrest Rubber LH	✓	35	✓
Rear Footrest Bracket. LH.	✓	58	✓
Rear LH Side Fairing	✓	108	✓
Rear Swing Arm.	✓	385	✓
Rear Shock Absorber	✓	250(SN)	X
Rear Wheel Rim.	✓	280(SN)	X
Rear Wheel Rim Spindle	✓	30.	✓
Rear LH Signal Lamp.	✓	28	✓

JSK 4363.

Reer Seat Handle. ^{Repr} 65 x

Reer Box ^{ut} 250(SN) ✓

Reer Box Bracket ^{MP} 250(SN) x
^{re}

Stickers. ^{New} ~~80(SN)~~ ✓ 50(SN)

S.N: 495

1395

1255-50

Panel Beating

Spray Painting.

Wiring.

To straighten chassis body

Towing Fees.

~~400~~ 200

~~350~~ 200

~~50~~ 30

~~200~~ 150

620

40. ✓

Total: 2370.50

h/s: 1.6K
(Nett Value)

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: