



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHEN XINYOU			Ref: CS/ASM21011122/Aty3e2 Date: 13/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6959C	Veh. Inspected	JSK 4363	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03KYG	Excess (\$)	0.00	
Assign From	CHEN XINYOU	Assign Date	01/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	PMYUG0420H0109725	Colour	BLACK	
Odometer	86666 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	MAXXIS	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	70/90 R17	MAXXIS	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2021	Inspection Date	01/11/2021	
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	