

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011126/BTY3N2**Date:** 11/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00127562101

**Claimant Vehicle
No :** SLX2993C**Insured Vehicle
No :** SJB5925U

Date of Loss: 28/10/2021

Nature of Claim: TP

Claim
No: SNM21D206170/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLX2993C**Make & Model: MERCEDES-BENZ CLA180, 1.6 AMG LINE (R18 BI)
(A)

Engine No: 27091030490591

Reg. Date: 07/01/2015 (Man. Year: 2014)

Chassis No: WDD1173422N134238

Colour: Red

Odometer: 162998 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size: 225/40R18

Front Left Side: LAUFENN 5 mm

Rear Left Side: Dayton 5 mm

Front Right Side: LAUFENN 5 mm

Rear Right Side: Dayton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,224.60	3,935.11	11,289.49	74.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	660.00	3,470.00	84.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,354.60	4,595.11	14,759.49	76.26
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	19,354.60	3,700.00	15,654.60	80.88
+ GST 7.00/7.00% (S\$)	1,354.82	259.00	1,095.82	80.88
Nett Amount (S\$)	20,709.42	3,959.00	16,750.42	80.88

INSPECTION

Date of Assignment: 04/01/2022

Date Inspected: 01/11/2021 Inspected At:

160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jan 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 AMG LINE (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLX2993C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Damaged	2,487.90 FL	*- FL
2	1		*BOOTLID LOGO	Not Damaged	110.00 FL	*- FL
3	1		*BOOTLID WEATHER STRIP	Not Damaged	168.00 FL	*- FL
4	1		*BOOTLID INNER LOCK ASSY	Not Damaged	274.00 FL	*- FL
5	1		*REAR BUMPER	Broken	1,786.00 FL	*1,350.00 FL
6	1		*REAR BUMPER LOWER	No such part	686.30 FL	*- FL
7	1		*REAR BUMPER LOWER CENTER GARNISH	Broken	275.30 FL	*156.68 FL
8	1		*REAR BUMPER REINFORCEMENT	Not Damaged	698.00 FL	*- FL
9	1		*REAR BUMPER CENTRE BEAM GARNISH	Broken	213.90 FL	*162.00 FL
10	3		*REAR BUMPER BRACKET	Not Damaged	435.00 FL	*- FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	312.00 FL	*250.00 FL
12	1		*REAR BUMPER REVERSE SENSOR (6 Pcs)	Short Circuit (2 Pcs only)	1,590.00 FL	*500.00 FL
13	1		*REAR BUMPER HEAT SHIELD	Not Damaged	288.00 FL	*- FL
14	1		*REAR BUMPER TOW CAP	Not Damaged	125.00 FL	*- FL
15	1		*REAR END PANEL OUTER	Repair	1,125.00 FL	*- FL
16	1		*REAR END PANEL INNER	Not Damaged	995.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Damaged	215.00 FL	*- FL
18	1		*TAILLAMP	O/s Broken	1,460.00 FL	*598.00 FL
19	2		*TAILLAMP OUTER GARNISH	No such part	360.00 FL	*- FL
20	1		*TAILLAMP BRACKET	O/s Broken	98.00 FL	*49.00 FL
21	2		*REAR EXHAUST PIPE CHROME TIP	Not Damaged	690.00 FL	*- FL
22	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Damaged	181.60 FL	*- FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*REAR BUMPER LOWER CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*REAR BUMPER REVERSE SENSOR SEAL (6 Pcs)	Necessary (2 Pcs only)	348.00 FS	*116.00 FS
28	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
30	2		*TAILLAMP CLIPS	No such part	120.00 FS	*- FS
31	1		*TAILLAMP SEAL	Necessary (1 Pc only)	120.00 FS	*30.00 FS
32	1		*BOOTLID WRAP STICKER }	Cut	480.00 FS	*1,000.00 FS
33	1		*REAR BUMPER WRAP STICKER }	Cut	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,682.00	4,241.68
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,457.40	306.57
Total Parts (\$\$)	15,224.60	3,935.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
2	R&R REAR EXHAUST PIPE	New	150.00	0.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
4	CONDUCT WATER LEAK TEST	New	180.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEATING	New	1,400.00	400.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,400.00	200.00
Gross Labour Cost (S\$)			4,130.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >