

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21011127/Uvf3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	11/11/2021		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJX 5990P	Veh. Inspected	ł	SMW 4040H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103237/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		01/11/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11111434	Colour		WHITE	
	Odometer	69923 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	TOYO		6 mm	
	L/H Front Tyre	215/60 R16	TOYO		6 mm	
	R/H Rear Tyre	215/60 R16	TOYO		6 mm	
	L/H Rear Tyre	215/60 R16	TOYO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	SUSTAINED DAMAGES AT THE FRONT AND REAR				
5.	5. General Information					
	Accident Date	29/10/2021	Inspect Date /	Time	01/11/2021 ( 03:00 PM )	
	Survey held at	rvey held at 3 MOTORWERKZ				
	25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/SMO21011127/Uvf3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser