

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21011129/KVF3N2**Date:** 24/11/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001361026
Claimant Vehicle No :	GBC6399X	Insured Vehicle No :	YP6088C
Date of Loss:	30/10/2021	Nature of Claim:	TP
		Claim No:	264819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6399X		
Make & Model:	TOYOTA DYNA 150 MANUAL, 3.0 D (M)	Engine No:	1KD2279496
Reg. Date:	22/04/2013 (Man. Year: 2013)	Chassis No:	JTFAT35Y40K202265
Colour:	Silver	Odometer:	349497 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8(D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,057.78	5,810.02	247.76	4.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	3,760.00	1,600.00	29.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,417.78	9,570.02	1,847.76	16.18
Approved Total (Overridden) (S\$)		7,450.00		
(S\$)	11,417.78	7,450.00	3,967.78	34.75
+ GST 7.00/7.00% (S\$)	799.24	521.50	277.74	34.75
Nett Amount (S\$)	12,217.02	7,971.50	4,245.52	34.75

INSPECTION

Date of Assignment:	01/11/2021		
Date Inspected:	02/11/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	12.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Nov 2021)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6399X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	398.57 FL	*398.57 FL
2	1		*FRONT GRILLE	Dented/Warped	516.60 FL	*516.60 FL
3	1		*FRONT GRILLE LOGO	Necessary	70.35 FL	*70.35 FL
4	1		*FRONT GRILLE INNER RUBBER	Necessary	40.80 FL	*40.80 FL
5	1		*RH HEADLAMP	Cracked	795.00 FL	*795.00 FL
6	1		*FRONT PANEL	Bent	1,126.00 FL	*1,126.00 FL
7	1		*FRONT PANEL EMBLEM	Necessary	70.90 FL	*70.90 FL
8	1		*FRONT PANEL TOP CENTRE GARNISH	Dented/Cut	342.80 FL	*342.80 FL
9	1		*FRONT CHASSIS CROSS MEMBER	Repair	222.60 FL	*- FL
10	1		*RH TAILLAMP	Cracked	210.70 FL	*210.70 FL
11	1		*RH TAILLAMP PANEL	Bent	102.80 FL	*102.80 FL
12	1		*FRONT LH SIDE MIRROR STAY	Bent	369.70 FL	*369.70 FL
13	1		*FRONT LH SIDE MIRROR ROUND	Missing	183.00 FL	*183.00 FL
14	1		*FRONT WINDSCREEN GLASS RUBBER (50%)	Necessary	242.42 FS	*161.61 FS
15	1		*FRONT NUMBER PLATE	Bent	18.00 FS	*18.00 FS
16	1		*STICKER-70KM/H	Necessary	10.00 FS	*10.00 FS
17	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
18	1		*FRONT RH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
19	1		*RH TAILGATE ASSY	Bent	900.00 FS	*900.00 FS
20	1		*RH CANOPY BOX PILLAR	Buckled	300.00 FS	*300.00 FS
21	1		*TAILGATE LOCK ASSY	Bent	480.00 FS	*480.00 FS
22	1		*RH TAILGATE LOWER HINGE	Bent	150.00 FS	*150.00 FS
23	1		*CANOPY REAR RH SIDE PANEL	Buckled	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,170.24	6,866.83
- List Item Discount on L Items 25.00/25.00% (\$)	1,112.46	1,056.81
Total Parts (\$)	6,057.78	5,810.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	New	250.00	250.00
2	REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
3	PUTTY & RESPRAY ON FRT PANEL,GRILLE,FRT RH DOOR,REAR RH PILLAR,BUMPER & ALL FRT AFFECTED AREAS	New	950.00	850.00
4	REMOVE & REFIX RH TAILGATE,RH SIDE GATE,TO CUT,WELD & RENEW REAR RH SIDE PANEL,REAR RH CORNAL PILLAR & REALIGN THE SAME INCLUDING SUPPLY ALL NECESSARY MAETRIAL }	New	1,500.00	1,500.00
5	REMOVE & REFIX RH TAILLAMP & PANEL.TO KNOCK & REPAIR REAR END FLOOR BOARD PANEL & REALIGN THE SAME INCLUDING REMOVE & REFIX REAR TRUCK }	New	1,000.00	0.00
6	PUTTY & RESPRAY ON RH TAILGATE,PILLAR.REAR END PANEL & ALL REAR AFFECTED AREAS	New	600.00	400.00
7	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	60.00	60.00
8	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL,FRT MAIN CHASSIS MEMBER & REALIGN THE SAME	New	900.00	600.00
Gross Labour Cost (\$\$)			5,360.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >