

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2111-230
DATE : 1-Nov-2021
POLICY NO. : DA MT/00752586/010
VEHICLE REG. NO. : SKZ3354S
VEHICLE MAKE : NISSAN / QASHQAI 1.2 DIG-T CVTTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

| NO. | DESCRIPTION | QUANTITY | UNIT COST | TOTAL COST |
|-----------------------------|---|----------|-----------|-------------|
| | <u>SPARE PARTS</u> | | | |
| 1 | Rear Bumper | 1 | \$ 820.00 | \$ 820.00 |
| 2 | Rear Bumper Clips | 10 | \$ 5.00 | \$ 50.00 |
| 3 | Rear Bumper Lower | 1 | \$ 520.00 | \$ 520.00 |
| 5 | Rear Reinforcement | 1 | \$ 700.00 | \$ 700.00 |
| 6 | Rear Reinforcement Bracket LH | 1 | \$ 150.00 | \$ 150.00 |
| 7 | Rear Sponge | 1 | \$ 140.00 | \$ 140.00 |
| 9 | Rear Retainer LH | 1 | \$ 50.00 | \$ 50.00 |
| 10 | Rear Fender Arc Garnish LH | 1 | \$ 500.00 | \$ 500.00 |
| 11 | Rear Fender Shield LH | 1 | \$ 220.00 | \$ 220.00 |
| 13 | Rear Tail Lamp LH | 1 | \$ 320.00 | \$ 320.00 |
| 14 | Rear Reflector LH | 1 | \$ 80.00 | \$ 80.00 |
| Total Spare Parts | | | | \$ 3,550.00 |
| | <u>SPECIAL NETT</u> | | | |
| 15 | Reverse Sensor | 1 | \$ 200.00 | \$ 200.00 |
| Total Special Nett | | | | \$ 200.00 |
| | <u>LABOUR</u> | | | |
| 16 | Spray Painting Rear Bumper, Tailgate, Rear Fender LH and End Panel include Blending | 1 | \$ 800.00 | \$ 800.00 |
| 17 | Repair and Replace Affected Accident Parts | 1 | \$ 800.00 | \$ 800.00 |
| 18 | Remove and Refit Rear Bumper Reverse Sensor | 1 | \$ 100.00 | \$ 100.00 |
| 19 | Remove and Replace Rear Exhaust Pipe and Silencer, Re-align | 1 | \$ 200.00 | \$ 200.00 |
| 20 | Apply Rust Proofing on Replaced/Repaired Panel | 1 | \$ 100.00 | \$ 100.00 |
| 21 | Check and Rectify Electrical Wiring | 1 | \$ 30.00 | \$ 30.00 |
| Total Labour | | | | \$ 2,030.00 |
| Amount Before Excess | | | | \$ 5,780.00 |
| Add GST @ 7% | | | | 404.60 |
| Total Amount Payable | | | | \$ 6,184.60 |

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.