

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Kwee Trading
C/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP19050021

Date: 17 Jul 2020

Vehicle no: GBG8833A

Model : TOYOTA HIACE

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 30 May 2019 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 630.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
TOTAL :		\$ 630.00

Notes :

- *1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP19050021

Date: 17 Jul 2020

Kwee Trading
C/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY ACCIDENT OCCURED ON 27 May 2019

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 30 May 2019
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
GBG8833A

1. VEHICLE PARTICULARS

Registration No : GBG8833A
Model : TOYOTA HIACE
Year / Capacity : Nov 2017 / 2799 cc
Chassis No : JTFHT02P800233345

Engine No : 1KD2750643
Mileage : 019 727 km
Colour : Metallic Silver

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBG8833A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front bumper	bent/distorted	\$ 1,408.00	\$ 1,408.00
2 pcs	Front bumper side retainer	deformed	\$ 88.00	\$ 88.00
2 pcs	Front bumper side attachment	distorted	\$ 64.00	\$ 64.00
1 pc	Front bumper reinforcement	dent/distorted	\$ 478.50	\$ 478.50
10 pcs	Front bumper clips	necessary	\$ 129.00	\$ 129.00
1 pc	Front grille	distorted	\$ 684.50	\$ 684.50
6 pcs	Front grille clips	necessary	\$ 77.40	\$ 77.40
2 pcs	Headlamp assembly	electronically shocked	\$ 950.00	\$ 950.00
4 pcs	Headlamp clips	necessary	\$ 50.00	\$ 50.00
1 pc	Front support panel	dent/distorted	\$ 574.80	\$ 574.80
1 pc	Bonnet	grazed/deformed	\$ 703.00	\$ 503.36
1 pc	Bonnet emblem	necessary	\$ 68.00	\$ 68.00
1 pc	Windscreen spare tank assembly	dent/distorted	\$ 383.65	\$ 383.65
1 pc	Sub frame sub member	distorted	\$ 121.50	\$ 121.50
1 pc	Reinforcement sub cross member	distorted	\$ 132.25	\$ 132.25
Parts Sub-Total			\$ 5,912.60	\$ 5,712.96
Discount 25.00%			\$ 1,478.15	\$ 1,428.24
			\$ 4,434.45	\$ 4,284.72

Vehicle Number : GBG8833A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Front number plate	distorted	\$ 65.00	\$ 65.00
Special Nett Sub-Total			\$ 65.00	\$ 65.00
Spare Parts Total			\$ 4,499.45	\$ 4,349.72

LABOUR COST


S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 4,499.45	\$ 4,349.72
1	Towing	\$ 120.00	\$ 120.00
2	To tuff coat affected areas	\$ 180.00	\$ 150.00
3	To remove and refix interior upholstery	\$ 250.00	\$ 240.00
4	To remove and refix radiator and top up coolant	\$ 180.00	\$ 150.00
5	To remove and refix air con condenser, piping, vacuum & top up gas	\$ 180.00	\$ 150.00
6	To respray affected areas	\$ 1,800.00	\$ 1,600.00
7	To renew damaged parts, straighten and repair front fender inner, front chassis member and aligned all parts	\$ 2,000.00	\$ 1,800.00
8	To check wiring system	\$ 180.00	\$ 150.00
	Total	\$ 9,389.45	\$ 8,709.72

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 7,400.00


Fong Kok Heng
Qualified Appraiser









1989/20: F












SURVEY



AUTOMAT

SURVEY



AUTOMATA



AUTOMAX SURVEY



AUTOMAX

SURVEY



AUTOMAX





TRAFFIC SURVEY

TRAFFIC SURVEY



