

# AUTOMOBILE INSPECTION SERVICES PTE LTD

Postal Address : BLK 146, POTONG PASIR AVE 1, #02-145 SINGAPORE 350146  
 Reg. No. 200005790R TEL NO : 62860155 ( 3 LINES) FAX : 62841539  
 SURVEY/ADJUSTING DAMAGES ON MOTOR VEHICLE , LICENSED APPRAISERS

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: IIIA/0065/20  
 Date: 28/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0000068  
 Claimant Vehicle No : GBG8833A Insured Vehicle No : YP5484Z  
 Date of Loss: 27/05/2019 Nature of Claim: TP Claim No: MCV2019D0000674

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG8833A  
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2750643  
 Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: JTFHT02P800233345  
 Colour: Silver Odometer: 19727 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 195/R15 Rear Tyre Size: 195/R15  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm  
*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,349.72	1,763.46	2,586.26	59.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	880.00	3,480.00	79.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,709.72</b>	<b>2,643.46</b>	<b>6,066.26</b>	<b>69.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,709.72</b>	<b>2,100.00</b>	<b>6,609.72</b>	<b>75.89</b>

### INSPECTION

Date of Assignment: 29/05/2019  
 Date Inspected: 31/05/2019, 03/06/2019, 06/06/2019 Inspected At: Eng Soon Painting Services (HQ)  
 393J WOODLANDS ROAD  
 Singapore 677978  
 Estimated Period of Repair: 4.0 days

Adjuster: LOOI

Manager: SOPHIA VA  
 (Administrator)

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DESCRIPTION OF DAMAGES

DAMAGED TO THE FRONT PORTION. (PLEASE REFER TO ATTACHED PHOTOS)

PRE-REPAIR SURVEY

AT THE TIME OF INSPECTION, NO ESTIMATE WAS PROVIDED AND REPAIRER IS ENGAGING THEIR OWN SURVEYOR.

(PRS ON 30/05/2019)

PAPER RE-SURVEY

AS PER YOUR INSTRUCTIONS ON 24/08/2020, TO CONDUCT A PAPER RE-SURVEY.

BASED ON THE DOCUMENTS PROVIDED, AFTER OUR ASSESSMENT, A LUMP SUM OF \$2,100.00 AND 4 DAYS IS SUFFICIENT FOR THE REPAIRS.

THE ABOVE IS ONLY OUR OPINION & SERVES AS A GUIDELINE FOR YOUR EASY SETTLEMENT.

LUMP SUM REPAIR RECOMMENDED BY THEIR SURVEYOR WAS \$7,400.00.

WE NOW LEAVE THE MATTER FOR YOUR FURTHER PERUSAL.

SPECIAL REMARKS

THIS SURVEY WAS CONDUCTED STRICTLY ON A "WITHOUT PREJUDICE" BASIS.

## REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 Aug 2020)  
**Parts:** 213      TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Automobile Inspection Services Pte Ltd/GBG8833A/28/08/2020 15:22  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (Price incorrect)	NECESSARY	1,408.00 FL	*622.16 FL
2	2		*FRONT BUMPER SIDE RETAINER (1PC RH)	NECESSARY	88.00 FL	*44.00 FL
3	2		*FRONT BUMPER SIDE ATTACHMENT	SERVICEABLE	64.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT (Price incorrect)	NECESSARY	478.50 FL	*395.91 FL
5	10		*FRONT BUMPER CLIPS	NECESSARY	129.00 FL	*20.00 FL
6	1		*FRONT GRILLE (Price incorrect)	NECESSARY	684.50 FL	*497.30 FL
7	6		*FRONT GRILLE CLIPS	NECESSARY	77.40 FL	*30.00 FL
8	2		*HEADLAMP ASSEMBLY (1PC RH)	NECESSARY	950.00 FL	*475.00 FL
9	4		*HEADLAMP CLIPS	NECESSARY	50.00 FL	*20.00 FL
10	1		*FRONT SUPPORT PANEL	SERVICEABLE	574.80 FL	*- FL
11	1		*BONNET	REPAIR	503.36 FL	*- FL
12	1		*BONNET EMBLEM	NECESSARY	68.00 FL	*68.00 FL
13	1		*WINDSCREEN SPARE TANK ASSEMBLY	SERVICEABLE	383.65 FL	*- FL
14	1		*SUB FRAME SUB MEMBER	SERVICEABLE	121.50 FL	*- FL
15	1		*REINFORCEMENT SUB CROSSMEMBER	NECESSARY	132.25 FL	*132.25 FL
16	1		*FRONT NUMBER PLATE	NECESSARY	65.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,777.96	2,339.62
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,428.24	576.16
Total Parts (\$\$)	4,349.72	1,763.46

Automobile Inspection Services Pte Ltd/GBG8833A/28/08/2020 15:22. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING	New	120.00	0.00
2	TO TUFF COAT AFFECTED AREAS	New	150.00	0.00
3	TO REMOVE AND REFIX INTERIOR UPHOLSTERY	New	240.00	0.00
4	TO REMOVE AND REFIX RADIATOR AND TOP UP COOLANT	New	150.00	0.00
5	TO REMOVE AND REFIX AIRCON CONDENSER, PIPING, VACUUM & TOP UP GAS	New	150.00	0.00
6	TO RESPRAY AFFECTED AREAS	New	1,600.00	450.00
7	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR FRONT FENDER INNER, FRONT CHASSIS MEMBER AND ALIGNED ALL PARTS	New	1,800.00	400.00
8	TO CHECK WIRING SYSTEM	New	150.00	30.00
Gross Labour Cost (S\$)			<b>4,360.00</b>	<b>880.00</b>

Automobile Inspection Services Pte Ltd/GBG8833A/28/08/2020 15:22. Not valid without Reference section.

< END OF ESTIMATES >