LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011138/T1QF3E2

Date: 07/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993682

Claimant Vehicle OBERGANA Province Vehicle No. 0999993682

No: Insured Vehicle No: GBK5940Y

Date of Loss: 04/10/2021 Nature of Claim: TP Claim No: 1369430162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE5276M

 Make & Model:
 TOYOTA DYNA 1.5T, 3.0 (A)
 Engine No:
 1KD2565022

 Reg. Date:
 04/01/2016 (Man. Year: 2015)
 Chassis No:
 KDY2318022160

 Colour:
 Blue
 Odometer:
 183290 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R13 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/11/2021

Date Inspected:

O1/11/2021 Inspected At:

Sunrise Auto Services (HQ)

BLK 15 DEFU LANE 10 #01-392

Singapore 539196

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$45,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT PANEL	Bent	0.00 F	*- F
2	1	*FRONT GRILLE	Cracked	0.00 F	*- F
3	1	*FRONT GRILLE EMBLEM	Cut	0.00 F	*- F
4	1	*FRONT BUMPER	Repair	0.00 F	*- F
5	1	*FRONT PANEL SEALANT	Necessary	0.00 F	*- F
6	1	*FRONT PANEL GARNISH CENTRE	Cut	0.00 F	*- F
F=Fra	nchise part.		_		
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >