

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011141/KPS3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100337286-08
Claimant Vehicle No :	SMR3276C	Insured Vehicle No :	SJD311M
Date of Loss:	30/10/2021	Nature of Claim:	TP
		Claim No:	2764336913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3276C	Engine No:	HR12128301K
Make & Model:	NISSAN SERENA, 2.0 (A)	Chassis No:	JN1EBAC27Z0000365
Reg. Date:	30/12/2019 (Man. Year: 2019)	Odometer:	50491 km
Colour:	Metallic Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,510.00	4,924.80	1,585.20	24.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,145.00	1,055.00	47.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,710.00	6,069.80	2,640.20	30.31
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	8,710.00	4,850.00	3,860.00	44.32
+ GST 7.00/7.00% (S\$)	609.70	339.50	270.20	44.32
Nett Amount (S\$)	9,319.70	5,189.50	4,130.20	44.32
+ Car Rental (4.0 x S\$80.00/day + 7.00% GST) (S\$)		342.40		
Nett Liability (S\$)		5,531.90		

INSPECTION

Date of Assignment:	01/11/2021	
Date Inspected:	08/11/2021	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,850.00 FN	*1,742.00 FN
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FN	*195.00 FN
3	1		*REAR TAILGATE HIGHWAY STAR EMBLEM	Necessary	55.00 FN	*55.00 FN
4	1		*REAR TAILGATE E-POWER EMBLEM	Necessary	75.00 FN	*75.00 FN
5	1		*REAR TAILGATE INNER LOCK	Dented	485.00 FN	*485.00 FN
6	1		*REAR TAILGATE INNER RUBBER	Dented / Cut	220.00 FN	*220.00 FN
7	1		*REAR TAILGATE INNER GARNISH	Mtg Cracked	580.00 FN	*580.00 FN
8	2		*REAR TAILLAMP LOWER GARNISH	Serviceable	510.00 FN	*- FN
9	1		*REAR BUMPER	Buckled	1,450.00 FN	*1,414.00 FN
10	1		*REAR BUMPER SIDE GARNISH	Serviceable	220.00 FN	*- FN
11	2		*REAR BUMPER PARKING SENSOR	Shorted	550.00 FN	*464.00 FN
12	2		*REAR BUMPER PARKING SENSOR RUBBER RING	Not Necessary	30.00 FN	*- FN
13	1		*REAR END PANEL	Repair	685.00 FN	*- FN
14	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	295.00 FN	*242.00 FN
15	1		*SET REAR NUMBER PLATE & CASING	Serviceable	30.00 FS	*- FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (\$\$)	7,230.005,472.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	720.00547.20
					Total Parts (\$\$)	6,510.004,924.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	80.00	15.00
2	TUFF KOTE	New	120.00	30.00
3	SPRAY PAINTING	New	1,000.00	600.00
4	LABOUR CHARGES	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,200.00	1,145.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >