

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM HAN CHUAN (LIN HANCHUAN)	Cust No/Name	/LIM HAN CHUAN (LIN HANCHUAN)
BLK 636 ANG MO KIO AVENUE 6	Reg No/Reg Date	SMK7001P / 06/05/201
#05-5165	Date In/Mileage	/ 0
SINGAPORE 560636	Chassis No	KNAF3416MK5036851
Contact No Mobile: 98188981	Engine No	G4FGJH720102
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	01/11/2021/ 15:22		442 / CocoLu	41879		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1920.00
RENEW FRT FENDER RH, FRT DOOR RH, WINDMIRROR RH							
E PNT98000							1650.00
SPRAY PAINT FOR FRT DOOR RH, FRT FENDER RH, WINDMIRROR RH							
E PNT88000							300.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS							
A 90000001							30.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							40.00
APPLY SEALANT FOR ACCIDENT							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							20.00
Sundry							
M PANEL-FENDER,RH				1.00	430.00	00.00	430.00
M INSULATOR-FENDER RH				1.00	27.00	00.00	27.00
M PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	00.00	1277.00
M HINGE ASSY-FRONT DOOR,RH				1.00	30.00	00.00	30.00
M HINGE ASSY-DOOR LOWER,RH				1.00	27.00	00.00	27.00
M BLACK TAPE-FR DR RR,RH				1.00	13.00	00.00	13.00
M MOULDING ASSY-FRT DR FRAME,RH				1.00	72.00	00.00	72.00
M W/STRIP ASSY-FR DR BELT O/S RH				1.00	80.00	00.00	80.00
M MIRROR ASSY-OUTSIDE RR VIEW,RH				1.00	559.00	00.00	559.00

Confirm & accepted by

7% GST on	Nett 6875.00	6,875.00 481.25
Total Payable		7,356.25

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.