

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21011143/EQF3N2**Date:** 23/11/2021**REFERENCE**

Insured/Claimant:	LIU JIALIANG, ERIC	Policy No:	1900091727
Date of Loss:	31/10/2021	Nature of Claim:	OD
		Claim No:	6192058360SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP996L	Engine No:	G4FGJH716118
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416MK5027626
Reg. Date:	21/05/2019 (Man. Year: 2018)	Odometer:	48635 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,083.00	4,217.60	1,865.40	30.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	2,970.00	620.00	17.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,673.00	7,187.60	2,485.40	25.69
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,073.00	6,587.60	2,485.40	27.39
+ GST 7.00/7.00% (S\$)	635.11	461.13	173.98	27.39
Nett Amount (S\$)	9,708.11	7,048.73	2,659.38	27.39

INSPECTION

Date of Assignment:	01/11/2021	
Date Inspected:	02/11/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
2	1		*GRILLE-FRONT BUMPER	Broken	485.00 F	*485.00 FL
3	1		*COVER-FR BUMPER FOG LAMP,LH	Broken	15.00 F	*15.00 FL
4	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 F	*- FL
5	1		*LAMP ASSY-FRONT FOG,LH	Not Necessary	303.00 F	*- FL
6	1		*MOULDING-FRONT BUMPER,LH	Broken	216.00 F	*216.00 FL
7	1		*LAMP ASSY-SIDE REPEATER,LH	Cut	143.00 F	*143.00 FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
9	1		*AIR DUCT-FR BUMPER,LH	Broken	14.00 F	*14.00 FL
10	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 F	*- FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
12	1		*ORNAMENT-KIA NO 115	Necessary	32.00 F	*32.00 FL
13	1		*LAMP ASSY-HEAD,LH	Cut	2,210.00 F	*2,210.00 FL
14	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
15	1		*CARRIER ASSY-FRONT END MODULE (Supplementary)	Broken	675.00 F	*675.00 FL
16	1		*BEAM COMPLETE-FR BUMPER (Supplementary)	Dented	497.00 F	*497.00 FL
17	10		*CLIPS (Supplementary)	Necessary	10.00 F	*10.00 FL
18	1		*WIRING ASSY-BUMPER EXTENSION (Supplementary)	Torn	207.00 F	*207.00 FL
19	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 F	*26.00 FL
					Sub Total (\$\$)	6,083.00 5,267.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 1,049.40
					Total Parts (\$\$)	6,083.00 4,217.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,REPAIR FRT FENDER LH	New	800.00	400.00
2	SPRAY PAINT FOR FRT BUMPER,FRT FENDER LH	New	700.00	480.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	800.00	800.00
6	REMOVE & REINSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR (Supplementary)	New	100.00	100.00
7	RESPRAY ON BONNET,RH FRONT FENDER (Supplementary)	New	960.00	960.00
8	VACUUM & TOP UP A/COND GAS (Supplementary)	New	80.00	80.00
Gross Labour Cost (\$\$)			3,590.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >