



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7951Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CUT	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET RH	NECESSARY	55.80	55.80
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER REINFORCEMENT BRACKET RH	SERVICEABLE	138.10	-
1	REAR BUMPER REFLECTOR LAMP RH	SERVICEABLE	41.45	-
	LESS 20% DISCOUNT		-312.56	-197.69
			1,250.24	790.76
<u>NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-	-18.00
			180.00	162.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		700.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			1,060.00	620.00
GRAND TOTAL			2,540.24	1,622.76

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,622.76
--	--	--	-----------------

Report Ref No. NS/INC21011153/Vucn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.