

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011162/APA3Q2**Date:** 24/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900017754-01
Claimant Vehicle No :	SLK8495C	Insured Vehicle No :	SMJ4611D
Date of Loss:	11/07/2021	Nature of Claim:	TP
		Claim No:	5736077833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8495C	Engine No:	CHZ156722
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V1HA058056
Reg. Date:	31/01/2017 (Man. Year: 2016)	Odometer:	74818 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,531.00	0.00	3,531.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,953.00	1,522.00	4,431.00	74.43
+ GST 7.00/7.00% (S\$)	416.71	106.54	310.17	74.43
Nett Amount (S\$)	6,369.71	1,628.54	4,741.17	74.43
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,830.54		

INSPECTION

Date of Assignment:	01/11/2021		
Date Inspected:	12/11/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,070.00 F	*- F
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 F	*- F
3	2		*REAR BUMPER LOCKING MECHANISM -LH/RH	Not Necessary	28.00 F	*- F
4	1		*REAR BUMPER ADAPTER -LH	Not Necessary	38.00 F	*- F
5	1		*REAR BUMPER SPOILER	Not Necessary	237.00 F	*- F
6	1		*REAR LIGHT REFLECTOR -LH	Not Necessary	30.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 F	*- F
8	1		*REAR BUMPER BRACKET -RH	Not Necessary	29.00 F	*- F
9	1		*REAR BUMPER BRACKET -LH	Not Necessary	27.00 F	*- F
10	1		*REAR BUMPER GUIDE SECTION -LH	Not Necessary	67.00 F	*- F
11	2		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 F	*- F
12	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	9.00 F	*- F
13	1		*SUNDRIES	Not Necessary	200.00 F	*- F
Total Parts (\$\$)						3,531.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >