12/14/21, 11:03 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21011164/VPA3Q2

**Date:** 14/12/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100311403

Claimant Vehicle

No: SHD1385S Insured Vehicle No: SDY1688E

Date of Loss: 31/10/2021 Nature of Claim: TP Claim No: 9840318770SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD1385S

Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M) Engine No: D4FBGZ122119

Reg. Date: 29/06/2017 (Man. Year: 2016) Chassis No: TMAD281UVHJ128027

Colour: Silver Odometer: 306721 km

Engine Capacity: 1582 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,322.55	1,577.26	4,745.29	75.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	780.00	1,460.00	65.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	8,562.55	2,357.26	6,205.29	72.47
Approved Total (Overridden) (S\$	5)	1,900.00		
(S\$	8,562.55	1,900.00	6,662.55	77.81
+ GST 7.00/7.00% (S\$	599.38	133.00	466.38	77.81
Nett Amount (S\$	9,161.93	2,033.00	7,128.93	77.81
+ Loss of Use (3.0	x S\$50.00/day) (S\$)	150.00		
+ Car Rental (3.0 x S\$62.06/day) (S\$)		186.18		
1+	Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	2,371.18		

**INSPECTION** 

Date of Assignment: 01/11/2021

Premier Automotive Services Pte Ltd (HQ)

Date Inspected: 02/11/2021 Inspected At: 23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOWER GARNISH	Cut	362.61 FL	*362.61 FL
2	1		*TAILGATE	Repair	2,292.30 FL	*- FL
3	2		*TAILGATE HINGE	Serviceable	57.00 FL	*- FL
4	1		*TAILGATE WEATHERSTRIP	Serviceable	276.98 FL	*- FL
5	1		*TAILGATE STRIKER	Serviceable	36.50 FL	*- FL
6	1		*TAILGATE EMBLEM 130	Necessary	27.80 FL	*27.80 FL
7	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
8	1		*EMBLEM HYUNDAI LOGO	Serviceable	29.40 FL	*- FL
9	1		*END PANEL	Serviceable	853.85 FL	*- FL
10	1		*REAR O/S TAIL LAMP	Serviceable	321.30 FL	*- FL
11	1		*REAR O/S REFLECTOR	Serviceable	295.10 FL	*- FL
12	1		*REAR N/S TAIL LAMP	Serviceable	321.30 FL	*- FL
13	1		*REAR N/S REFLECTOR	Serviceable	295.10 FL	*- FL
14	1		*REAR BUMPER	Cut	811.11 FL	*811.11 FL
15	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL
18	2		*REAR BUMPER O/S & N/S SIDE BRACKET	Necessary	104.40 FL	*104.40 FL
19	1		*REAR BUMPER N/S & O/S REFLECTOR	N/S Serviceable /O/S Scratched	107.50 FL	*53.75 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
21	1		*SET REVERSE SENSOR	Cut	280.00 FS	*280.00 FS
22	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
23	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
24	1		*SEALANT	Not Necessary	50.00 FS	*- FS
25	1		*SUNDRY	Serviceable	50.00 FS	*- FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	7,761.69	1,855.07
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,439.14	277.81	
				Total Parts (S\$)	6,322.55	1,577.26
			Report was unsubmitted	during this print-out		

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=1042853&extid=372803&CFID=90320... 3/4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	30.00
2	TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE TAILGATE INTO NEW TAILGATE ,TEST WIPER MOTOR AND WATER ETC	New	120.00	0.00
3	TO DISMANTLE AND REFIT THE REAR WINDSCREEN	New	120.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL ETC	New	900.00	360.00
5	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL	New	900.00	360.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
	Gross Labour Cost (S\$)		2,240.00	780.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >