

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011165/APA3Q2**Date:** 21/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993650
Claimant Vehicle No :	SMU6813S	Insured Vehicle No :	GBJ8790Z
Date of Loss:	21/10/2021	Nature of Claim:	TP
		Claim No:	0048771194SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU6813S	Engine No:	1AZ5549410
Make & Model:	TOYOTA PICNIC, 2.0 (A)	Chassis No:	JTEGH23B400023146
Reg. Date:	10/01/2007 (Man. Year: 2006)	Odometer:	190778 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,021.47	1,745.62	3,275.85	65.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	880.00	2,200.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,101.47	2,625.62	5,475.85	67.59
Approved Total (Overridden) (\$\$)		2,100.00		
Nett Amount (\$\$)	8,101.47	2,100.00	6,001.47	74.08
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	01/11/2021	Lee Sheng Auto Pte Ltd (HQ)
Date Inspected:	01/11/2021 Inspected At:	1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	685.00 FL	*685.00 FL
2	1		*FRONT FENDER INNER SHIELD REPAIR	Torn	185.00 FL	*185.00 FL
3	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	35.00 FL	*35.00 FL
4	1		*FRONT BUMPER	Distorted	785.00 FL	*785.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.00 FL	*- FL
6	1		*FRONT BUMPER RETAINER LH	Not Necessary	24.50 FL	*- FL
7	1		*FRONT BUMPER RETAINER RH	Damaged	24.50 FL	*24.50 FL
8	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	250.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP BRACKET RH	Not Necessary	85.50 FL	*- FL
10	1		*FRONT BUMPER FOAM	Not Necessary	78.00 FL	*- FL
11	1		*FRONT BUMPER BRACKET RH	Not Necessary	26.80 FL	*- FL
12	1		*SPARE TANK	Not Necessary	250.00 FL	*- FL
13	1		*BONNET	Not Necessary	1,475.00 FL	*- FL
14	1		*GRILLE	Not Necessary	450.00 FL	*- FL
15	1		*BONNET LOCK	Not Necessary	185.00 FL	*- FL
16	1		*BONNET HINGE RH	Not Necessary	95.00 FL	*- FL
17	1		*BONNET HINGE LH	Not Necessary	95.00 FL	*- FL
18	1		*SUPPORT PANEL	Not Necessary	480.00 FL	*- FL
19	1		*FRONT BUMPER UNDER COVER	Not Necessary	450.00 FL	*- FL
20	1		*VVTI EMBLEM	Necessary	38.00 FL	*38.00 FL
21	1		*TOYOTA LOGO	Not Necessary	38.00 FL	*- FL
22	1		*HEADLAMP	Cut	575.00 FL	*575.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,695.30	2,327.50
- List Item Discount on L Items 25.00/25.00% (\$)	1,673.83	581.88
Total Parts (\$)	5,021.47	1,745.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING ,JACKING FRONT PORTION	New	1,200.00	400.00
2	SPRAY FRONT BONNET ,FENDER ,BUMPER ,SUPPORT	New	1,500.00	400.00
3	WIRING	New	50.00	30.00
4	ALIGNMENT	New	80.00	0.00
5	ANTI BUSH ON AFFECTED AREA	New	250.00	50.00
Gross Labour Cost (S\$)			3,080.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >