

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011167/EQF3E2**Date:** 22/11/2021**REFERENCE**

Insured/Claimant: NOR HASHIM BIN MOHAMAD ISA Policy No: 2070110605
Date of Loss: 30/10/2021 Nature of Claim: OD Claim No: 7983614508SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU1147P**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UJB1536
Reg. Date: 29/07/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH003348
Colour: Red Odometer: 15820 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,255.32	891.64	1,363.68	60.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,135.00	1,395.00	39.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,785.32	3,026.64	2,758.68	47.68
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,185.32	2,426.64	2,758.68	53.20
+ GST 7.00/7.00% (S\$)	362.97	169.86	193.11	53.20
Nett Amount (S\$)	5,548.29	2,596.50	2,951.79	53.20

INSPECTION

Date of Assignment: 02/11/2021
Date Inspected: 02/11/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*UNPAINTED BODYKITS	Repair	1,643.00 FN	*- FN
3	1		*LAMP ASSY, COMB, RR LH	Broken	337.00 FL	*337.00 FL
4	1		*REFLECTOR LH	Not Necessary	23.00 FL	*- FL
5	1		*FACE, RR BUMPER	Broken	751.00 FL	*751.00 FL
6	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
7	4		*CLIP, FR BUMPER	Necessary	4.00 FL	*4.00 FL
8	1		*MUD GUARD, RR LH	Not Necessary	41.00 FL	*- FL
9	3		*CLIPS (Supplementary)	Necessary	12.00 FL	*12.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	2,859.00	1,152.00
- List Item Discount on L Items 23.00/23.00% (S\$)	275.08	260.36
- Nett Item Discount on N Items 20.00/20.00% (S\$)	328.60	0.00
Total Parts (S\$)	2,255.32	891.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER & RR BUMPER BODY KIT. REPAIR LHR FENDER & RR END PNL	New	1,800.00	755.00
2	RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL & LHR FENDER	New	1,400.00	1,050.00
3	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO GIVE WAY FOR REPAIR	New	120.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (\$)			3,530.00	2,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >