



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 3731T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	195.00	195.00
1	VISOR	CUT	250.00	250.00
1	SET FORK TUBE	TWISTED / DISTORTED	560.00	560.00
1	FRONT RH SIDE PANEL	SERVICEABLE	195.00	-
1	FRONT LH SIDE PANEL	CUT	205.00	205.00
1	COMPARTMENT PANEL	MTG CRACKED	195.00	195.00
2	FLOOR BOARD L/RH	DEEP CUT	300.00	300.00
2	LOWER PANEL L/RH	DEEP CUT	260.00	260.00
1	HEAD LAMP ASSY	CUT	560.00	560.00
1	REAR SIDE PANEL LH	CUT	165.00	165.00
1	FRONT MUDGUARD	DENTED / CUT	250.00	250.00
1	SET MIRROR	CUT	120.00	120.00
1	SET BRAKE LEVER L/RH	DENTED / CUT	150.00	150.00
1	SET THROTTLE GRIP	SERVICEABLE	180.00	-
1	EXHAUST GUARD	DENTED	195.00	195.00
	LESS 10% DISCOUNT		-189.00	-170.25
			3,591.00	3,234.75
	<u>LABOUR</u>			
	TOWING FEE.		40.00	30.00
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.		280.00	150.00
	REMOVE & REPLACE FORK TUBE,TOP UP FORK OIL.		120.00	100.00
	PUTTY RESPRAY PAINT.	NOT NECESSARY	420.00	-
			860.00	280.00
	GRAND TOTAL		4,451.00	3,514.75

Report Ref No. CS/SMO21011172/Ktf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	-----------------

Report Ref No. CS/SMO21011172/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.