

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21011175/R1TF3E2

Date: 07/12/2021

REFERENCE

Insured/Claimant: Million Auto Service Policy No: D20MFL0002382_01
Date of Loss: 29/10/2021 Nature of Claim: OD Claim No: MFL2021D0004760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG5234Z**
Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D057445
Reg. Date: 29/08/2017 (Man. Year: 2017) Chassis No: VSKYBAM20Z0146420
Colour: Grey Odometer: 133789 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,785.10	4,073.00	4,712.10	53.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,450.00	2,280.00	61.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,515.10	5,523.00	6,992.10	55.87
Approved Total (Overridden) (S\$)		4,400.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	10,515.10	2,400.00	8,115.10	77.18
+ GST 7.00/7.00% (S\$)	736.06	168.00	568.06	77.18
Nett Amount (S\$)	11,251.16	2,568.00	8,683.16	77.18

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021 Inspected At:

Million Auto Service (HQ)
4 Penjuru Place
#01-12 2.8 Penjuru Tech Hub
Singapore 608782

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5234Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	275.00 F	*275.00 F
2	2		*FRONT BUMPER SIDE RETAINER (WCP)	Necessary	44.00 F	*44.00 F
3	2		*FRONT BUMPER FOGLAMP (WCP)	Not Necessary	350.00 F	*- F
4	2		*FRONT BUMPER SIDE GARNISH (WCP)	Not Necessary	450.00 F	*- F
5	1		*FRONT BUMPER SPONGE (WCP)	Cracked	125.00 F	*125.00 F
6	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	285.00 F	*285.00 F
7	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	175.00 F	*175.00 F
8	1		*RADIATOR GRILLE (WCP)	Cracked	170.00 F	*170.00 F
9	1		*RADIATOR GRILLE EMBLEM (WCP)	Missing	45.00 F	*45.00 F
10	1		*RADIATOR GRILLE LOWER MOULDING (WCP)	Scratched	75.00 F	*75.00 F
11	2		*HEADLAMP ASSY (WCP)	Cracked	450.00 F	*450.00 F
12	2		*HEADLAMP LOWER BRACKET (WCP)	Serviceable	90.00 F	*- F
13	1		*HEADLAMP PANEL (WCP)	N/S Bent / O/S Repair	130.00 F	*65.00 F
14	2		*FRONT FENDER (WCP)	Not Necessary	630.00 F	*- F
15	2		*FRONT FENDER SIGNAL LAMP (WCP)	Not Necessary	66.00 F	*- F
16	2		*FRONT FENDER INNER SHIELD (WCP)	Not Necessary	210.00 F	*- F
17	1		*FRONT BONNET (WCP)	Bent	550.00 F	*550.00 F
18	1		*FRONT BONNET LOCK (WCP)	Bent	45.00 F	*45.00 F
19	2		*FRONT BONNET HINGE (WCP)	Bent	56.00 F	*56.00 F
20	1		*FRONT BONNET INSULATOR (WCP)	Not Necessary	65.00 F	*- F
21	1		*FRONT SUPPORT PANEL TOP (WCP)	Bent	300.00 F	*300.00 F
22	2		*FRONT SUPPORT PANEL SIDE (WCP)	Not Necessary	80.00 F	*- F
23	2		*AIR GUIDE LOWER (WCP)	Cracked	90.00 F	*90.00 F
24	2		*AIR GUIDE UPPER (WCP)	Cracked	80.00 F	*80.00 F
25	1		*AIRCON CONDENSER ASSY (WCP)	Bent	400.00 F	*400.00 F
26	1		*AIRCON DISCHARGE HOSE (WCP)	Not Necessary	210.00 F	*- F
27	1		*AIRCON SUCTION PIPE (WCP)	Not Necessary	200.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RADIATOR ASSY (WCP)	Cracked	350.00 F	*350.00 F
29	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	105.00 F	*- F
30	1		*RADIATOR LOWER HOSE (WCP)	Not Necessary	85.00 F	*- F
31	1		*RADIATOR SPARE TANK (WCP)	Not Necessary	55.00 F	*- F
32	1		*TURBO INTERCOOLER (WCP)	Not Necessary	680.00 F	*- F
33	1		*TURBO AIR INLET HOSE (WCP)	Not Necessary	95.00 F	*- F
34	1		*FAN MOTOR ASSY (WCP)	Not Necessary	300.00 F	*- F
35	1		*HORN (WCP)	Not Necessary	35.00 F	*- F
36	1		*WIPER WASHER TANK (WCP)	Not Necessary	185.00 F	*- F
37	1		*AIR DUCT (WCP)	Not Necessary	105.00 F	*- F
38	1		*FRONT NUMBER PLATE	Cracked	60.00 FS	*35.00 FS
39	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*RADIATOR GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	60.00 FS	*- FS
44	1		*RADIATOR COOLANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,021.00	3,715.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	764.10	358.00
Total Parts (\$\$)	8,785.10	4,073.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	500.00
2	TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	New	100.00	40.00
3	TO CHECK WIRING AND LIGHTING FUNCTION	New	80.00	30.00
4	TO REMOVE AND INSTALL AIR CON CONDENSER, FAN MOTOR, RADIATOR, TURBO INTERCOOLER AND TOP UP GAS	New	200.00	100.00
5	TO PROGRAMMED DIAGNOSTIC CHECK	New	150.00	80.00
6	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS	New	1,600.00	700.00
			Gross Labour Cost (\$\$)	3,730.00
				1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >