

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011177/KQY3N2**Date:** 25/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00069252101

Claimant Vehicle No : SJD8867Z **Insured Vehicle No :** GBJ8381X

Date of Loss: 01/11/2021 Nature of Claim: TP Claim No: SNM21D206231/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD8867Z**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRX417656

Reg. Date: 05/06/2014 (Man. Year: 2014) Chassis No: MR053REH104509170

Colour: Metallic Silver Odometer: 103501 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Toyo 5 mm Rear Left Side: Toyo 7 mm

Front Right Side: Toyo 5 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,090.00	1,489.60	600.40	28.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	2,040.00	250.00	10.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,380.00	3,529.60	850.40	19.42
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	4,380.00	3,500.00	880.00	20.09
+ GST 7.00/7.00% (S\$)	306.60	245.00	61.60	20.09
Nett Amount (S\$)	4,686.60	3,745.00	941.60	20.09

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Woodlands)
38 Woodlands Industrial Park E1, #05-04/05
Singapore 757700

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD8867Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	195.00 F	*195.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	125.00 F	*- FL
3	1		*REAR BUMPER LH REFLECTOR	Serviceable	28.00 F	*- FL
4	1		*REAR BUMPER SIDE RETAINER	Distorted	42.00 F	*42.00 FL
5	6		*REAR BUMPER CLIPS	Necessary	12.00 F	*12.00 FL
6	1		*REAR BOOT	Bent	350.00 F	*350.00 FL
7	1		*REAR BOOT INNER LOCK	Repair	135.00 F	*- FL
8	1		*REAR BOOT INNER RUBBER	Cut	55.00 F	*55.00 FL
9	1		*REAR BOOT LH REFLECTOR	Cracked	50.00 F	*50.00 FL
10	1		*REAR BOOT LOGO	Necessary	32.00 F	*32.00 FL
11	1		*REAR BOOT EMBLEM (COROLLA)	Necessary	28.00 F	*28.00 FL
12	1		*REAR BOOT EMBLEM (ALTIS)	Necessary	28.00 F	*28.00 FL
13	1		*REAR LH FENDER	Bent	380.00 F	*380.00 FL
14	1		*REAR PANEL	Bent	210.00 F	*210.00 FL
15	1		*TAILLAMP LH	Cracked	180.00 F	*180.00 FL
16	1		*SET REVERSE SENSOR	Dented/Shorted	200.00 FS	*200.00 FS
17	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,090.00	1,802.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	312.40
Total Parts (\$\$)	2,090.00	1,489.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING GARNISH	New	100.00	100.00
3	RENEW REAR LH FENDER & REAR PANEL	New	1,100.00	950.00
4	PUTTY & RESPRAY ON REAR LH FENDER, REAR END PANEL, BOOT, REAR BOOT, REAR BUMPER	New	900.00	800.00
5	REMOVE & REFIX REVERSE CAMERA, SENSOR & RESET SYSTEM	New	30.00	30.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$)			2,290.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >