

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7024A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER ASSY-RR BUMPER	CUT	553.00	553.00
1	COVER-RR BUMPER LWR	SCRATCHED	228.00	228.00
1	ABSORBER-RR BUMPER ENERGY	SERVICEABLE	119.50	-
1	BEAM-RR BUMPER	SERVICEABLE	428.40	-
1	STAY-RR BUMPER RH	DISTORTED	160.60	160.60
1	STAY-RR BUMPER LH	DISTORTED	160.60	160.60
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	EMBLEM-CRDI	NECESSARY	52.40	52.40
1	EMBLEM-140	NECESSARY	67.90	67.90
1	MLDG-BACK PANEL	DENTED	227.90	227.90
1	MLDG-CR PIECE	NECESSARY	85.00	85.00
1	PANEL ASSY-BACK	SERVICEABLE	526.70	-
	LESS 20% DISCOUNT		-526.40	-311.48
			2,105.60	1,245.92
	NETT ITEMS			
1	VEHICLE NUMBER PLATE REAR (N)	SCRATCHED	50.00	50.00
	LESS 10% DISCOUNT		-5.00	-5.00
			45.00	45.00
	SPECIAL NETT ITEMS			
1	PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	560.00
	SPRAYPAINT CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	20.00
	TUFF COAT ON AFFECTED PARTS.		50.00	20.00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR.		50.00	20.00
			1,350.00	1,120.00
	GRAND TOTAL		3,550.60	2,460.92

RECOMMENDED COST OF LUMP SUM REPAIRS		1,950.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21011179/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser