



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9108P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	459.40	459.40
1	REAR BUMPER MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER BRACKET RH	NECESSARY	55.80	55.80
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	41.50	-
1	REAR WHEEL COVER RH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	346.40	-
	LESS 20% DISCOUNT		-270.87	-193.29
			1,083.48	773.16
LABOUR				
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	REMOVE / REFIX REAR UPHOLSTERY.		90.00	30.00
	TUFF COATING.	NOT NECESSARY	90.00	-
	CHECK WIRING.		60.00	20.00
			1,440.00	650.00
GRAND TOTAL			2,523.48	1,423.16
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,423.16

Report Ref No. NS/INC21011180/Vvce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.