

REPAIR ESTIMATE*

VEHICLE NO **SHA9108P**

DATE **28/10/2021**

MAKE **:REG 02.07.2019**

MODEL **: HYUNDAI IONIQ**

/ CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER MOULDING			\$451.25
1	REAR BUMPER BRACKET RH			\$55.80
1	REAR BUMPER REFLECTOR RH			\$41.50
1	REAR WHEEL COVER RH <small>scratched</small>			\$346.40
	SUB TOTAL			\$1,354.35
	LESS 20%			\$270.87
	DISCOUNTED TOTAL			\$1,083.48
				\$-
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Remove/Refix rear upholstery			\$90.00
	Tuff coating			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$1,440.00
	ESTIMATE TOTAL			\$2,523.48
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Handwritten notes:
 CCB
 SCF
 SUC
 NC
 ✓
 350
 250
 30
 20XNN
 20
 ✓

Handwritten notes:
 Thuan@Lkhauto - low
 82235759
 29/10/21 1600
 L/S after repair photo
 2 days swap

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: