

Our Job Ref No : 305492506

Date : 06/11/21

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHA9108P

28/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


Z	The repair job shall bill to:	<u>NTUC</u>	<u>WC4347K</u>
2.	The finalized amount shall be:		
	(a) Spare Parts after List discount		<u>\$773.16</u>
	(b) Labour Charges		<u>\$650.00</u>
	Total for Part-By-Part Repair Cost		<u>\$1,423.16</u>
	(c) Lumpsum Repair (if applicable)		
	Total for Lumpsum repair cost after Less:		
	Final Lumpsum Repair cost		

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : thevan

Date : 8/11/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO **SHA9108P**

DATE **28/10/2021**

MAKE **:REG 02.07.2019**

MODEL **: HYUNDAI IONIQ**

/ CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER MOULDING			\$451.25
1	REAR BUMPER BRACKET RH			\$55.80
1	REAR BUMPER REFLECTOR RH			\$41.50
1	REAR WHEEL COVER RH			\$346.40
	SUB TOTAL			\$1,354.35
	LESS 20%			\$270.87
	DISCOUNTED TOTAL			\$1,083.48
				\$-
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Remove/Refix rear upholstery			\$90.00
	Tuff coating			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$1,440.00
	ESTIMATE TOTAL			\$2,523.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@Lkhauto - low
 82235759
 29/10/21 1600
 L/S after repair photo
 2 days swap

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305492506
 REGN NO : SHA9108P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 02.07.2019
 DATE/TIME IN : 28.10.2021 15:00
 ACCIDENT DATE : 28.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64

SUB-TOTAL : 773.16

JOB NATURE

0000	PB	PANEL BEATING - SHA9108P				350.00
0001	SP	SPRAYPAINT CHARGE				250.00
0002	20-05	REMOV/REFIX REVERES SENSOR-				30.00
0003	20-00	TUFF COAT ON AFFECTED PARTS.				20.00

SUB-TOTAL : 650.00

TOTAL : 1,423.16

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :