



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3589H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	CUT	553.00	553.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
1	REAR BUMPER UNDER COVER	DISLODGE	228.00	228.00
	LESS 20% DISCOUNT		-246.28	-160.60
			985.12	642.40
	<u>NETT ITEMS</u>			
1	REAR REVERSE SENSOR (N)	CUT	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER PROTECTOR (SN)	SCRATCHED	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		420.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
	CHECK LIGHTING & WIRING.		40.00	20.00
			820.00	570.00
	GRAND TOTAL		1,977.25	1,384.53
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			900.00

Report Ref No. NS/INC21011182/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.