

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21011184/ETCN2**Date:** 24/11/2021**REFERENCE**

Insured/Claimant:	PRIYANKA RANADE	Policy No:	1800021378
Date of Loss:	01/11/2021	Nature of Claim:	OD
		Claim No:	0194604698SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8474A		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT SUNROOF (A)	Engine No:	4J11XM1892
Reg. Date:	05/03/2018 (Man. Year: 2017)	Chassis No:	GF7W0401155
Colour:	Red	Odometer:	34969 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,376.48	5,026.68	1,349.80	21.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,995.00	835.00	29.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,206.48	7,021.68	2,184.80	23.73
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,606.48	6,421.68	2,184.80	25.39
+ GST 7.00/7.00% (S\$)	602.45	449.52	152.93	25.38
Nett Amount (S\$)	9,208.93	6,871.20	2,337.73	25.39

INSPECTION

Date of Assignment:	02/11/2021	
Date Inspected:	02/11/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,RH	Broken	2,135.00 FL	*2,135.00 FL
2	1		*LAMP ASSY,FOG,FRT RH	Not Necessary	348.00 FL	*- FL
3	1		*FACE,FR BUMPER	Broken	863.00 FL	*863.00 FL
4	1		*EXTENSION,FR BUMPER	Not Necessary	428.00 FL	*- FL
5	1		*BRACKET,FR BUMPER SIDE,RH	Broken	18.00 FL	*18.00 FL
6	1		*GARNISH,FR BUMPER,RH	Cut	75.00 FL	*75.00 FL
7	1		*BRKT,FR BUMPER SIDE,LWR RH	Broken	6.00 FL	*6.00 FL
8	1		*GARNISH,FR BUMPER SIDE	Cut	112.00 FL	*112.00 FL
9	1		*GARNISH,FR BUMPER SIDE	Cut	220.00 FL	*220.00 FL
10	1		*COVER,FR BUMPER	Not Necessary	295.00 FL	*- FL
11	1		*GARNISH,FR BUMPER SIDE	Cut	48.00 FL	*48.00 FL
12	1		*REINFORCEMENT,FR BUMPER	Not Necessary	505.00 FL	*- FL
13	1		*FENDER,FR RH	Dented	622.00 FL	*622.00 FL
14	1		*SHIELD,FR WHEELHOUSE,RH	Not Necessary	164.00 FL	*- FL
15	1		*MOULDING,FR BUMPER,RH	Cut	116.00 FL	*116.00 FL
16	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
17	1		*MOULDING,FR WHEEL ARCH,RH	Necessary	199.00 FL	*199.00 FL
18	1		*AERO KIT-OUTLANDER	Broken	1,554.00 FS	*1,554.00 FS
19	1		*RIVET, FR BUMPER (6PCS) (Supplementary)	Necessary	30.00 FL	*30.00 FL
20	1		*CLIP, FR BUMPER (10PCS) (Supplementary)	Necessary	40.00 FL	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,808.00	6,058.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,431.52	1,031.32
Total Parts (S\$)	6,376.48	5,026.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER,BODY KIT & AFFECTED AREA	New	1,350.00	675.00
2	PAINT WORK ON FRT BUMPER,FRT RH FENDER & FRT RH DOOR	New	1,050.00	1,050.00
3	REMOVE & REPLACE BODY KIT	New	80.00	80.00
4	PERFORM RUST PREVENTION	New	40.00	40.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	40.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			2,830.00	1,995.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >